

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III

841 Chestnut Building Philadelphia, Pennsylvania 19107

.SEP 8 1989

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Art Dalla Piazza
Department of Environmental Resources
Bureau of Solid Waste Management
7th Floor, Fulton Bldg.
P.O. Box 2063
Harrisburg, PA 17120

Site Inspections

Re: Penn Rare Metals PA-1216
Dublin Water Supply
Hilltown Quarry PA-655

Preliminary Assessments

Acro-Matic Inc. PA-2484
National can Company PA-2454
Prior Coated Metals PA-2437
Brintec Corp. PA-2401
CRC Chemicals Inc. PA-2403

Dear Mr. Dalla Piazza:

We are forwarding to you a copy of the final reports for the above referenced projects.

If there are any questions concerning the report please call me at 215-597-1073.

Sincerely,

Paul Racette

Pre-Remedial Section

Enclosure

cc: George Danyliw, DER (w/encls)

R-585-5-9-49

**ENVIRONMENTAL PRIORITIES INITIATIVE** PRELIMINARY ASSESSMENT OF NATIONAL CAN CORPORATION PREPARED UNDER

> TDD NO. F3-8903-38 EPA NO. PA-2454 CONTRACT NO. 68-01-7346

> > FOR THE

HAZARDOUS SITE CONTROL DIVISION U.S. ENVIRONMENTAL PROTECTION AGENCY

AUGUST 21, 1989

NUS CORPORATION SUPERFUND DIVISION

SUBMITTED BY

**REVIEWED BY** 

GARTH GLENN

APPROVED BY

REGIONAL OPERATIONS

MANAGER, FIT 3

PROJECT MANAGER

**SECTION SUPERVISOR** 

# Site Name: National Can Corporation TDD No.: F3-8903-38

### **TABLE OF CONTENTS**

SECTION		<u>PAGE</u>
1.0	INTRODUCTION	. 1-1
1.1	AUTHORIZATION	. 1-1
1.2	SCOPE OF WORK	. 1-1
1.3	SUMMARY	. 1-1
2.0	THE SITE	. 2-1
2.1	LOCATION	. 2-1
2.2	SITE LAYOUT	. 2-1
2.3	OWNERSHIP HISTORY	. 2-4
2.4	SITE USE HISTORY	
2.5	PERMIT AND REGULATORY ACTION HISTORY	. 2-5
2.6	REMEDIAL ACTION TO DATE	. 2-5
3.0	ENVIRONMENTAL SETTING	
3.1	WATER SUPPLY	
3.2	SURFACE WATERS	-
3.3	HYDROGEOLOGY	
3.3.1	GEOLOGY	. 3-3_
3.3.2	SOILS	
3.3.3	GROUNDWATER	
3.4	CLIMATE AND METEOROLOGY	. 3-7
3.5	LAND USE	. 3-7
3.6	POPULATION DISTRIBUTION	. 3-8
3.7	CRITICAL ENVIRONMENTS	. 3-8
4.0	WASTE TYPES AND QUANTITIES	A 4
4.0	·	
4.1	SOLID WASTE MANAGEMENT UNITS	
4.1.1	UNDERGROUND STORAGE TANKS	
4.1.2	DRUM STORAGE ROOM	
4.1.3	DRUM STORAGE PAD	
4.1.4	WASTE SOLVENT TANK	
4.1.5	HAZARDOUS WASTE STORAGE AREA	. 4-8
5.0	FIELD TRIP REPORT	5-1
5.1	SUMMARY	
5.2	PERSONS CONTACTED	
5.2.1	PRIOR TO FIELD TRIP	
5.2.2	AT THE SITE	
5.2.3	WATER SUPPLY WELL INFORMATION	
5.2.3 5.3	SITE OBSERVATIONS	
5.4	PHOTOGRAPH LOG	
5.5	EPA PRELIMINARY ASSESSMENT FORM	•
6.0	REFERENCES FOR SECTIONS 1.0 THROUGH 5.0	. 6-1

Site Name: National Can Corporation
TDD No.: F3-8903-38

### **APPENDICES**

Α	1.0 NOTIFICATION OF HAZARDOUS WASTE ACTIVITY AND HAZARDOUS WASTE PERMIT APPLICATION (PART A)	A-1
В	1.0 PERMIT-RELATED CORRESPONDENCE	B-1
С	1.0 FACILITY PHOTOGRAPHS	C-1

SECTION 1

TDD No.: <u>F3-8903-38</u>

1.0 INTRODUCTION

1.1 <u>Authorization</u>

NUS Corporation performed this work under Environmental Protection Agency Contract No. 68-01-

7346. This specific report was prepared in accordance with Technical Directive Document No. F3-

8903-38 for the National Can Corporation site, located in Morrisville, Pennsylvania.

1.2 Scope of Work

NUS FIT 3 was tasked to conduct an Environmental Priorities Initiative (EPI) preliminary assessment of

the subject site.

1.3 Summary

The National Can Corporation site is located nearly three miles southeast of the Morrisville city limits

in Falls Township, Bucks County, Pennsylvania. The site consists of approximately 16-1/2 acres of land

located in a large industrial park. U.S. Steel, which owns the subject site, has a facility located

between 1/2 and two miles east and southeast of the site.

In 1967, National Can Corporation (currently known as American National Can Company) leased the

subject property for 99 years from U.S. Steel. A building was constructed on site, and National Can

Corporation began metal-can-manufacturing processes at the facility. In 1983, after a few years of

scaling down its operations, National Can Corporation vacated the facility and subsequently

subleased the building as a warehouse. The building currently stores Lenox china, automobile tires,

and various paper products.

Waste materials produced by National Can Corporation at the subject facility included waste solvents,

waste vinyls, waste paint primers, waste varnishes, and a waste end sealing compound. Wastes were

not stored for more than 90 days. Five solid waste management units (SWMUs) have been identified

for National Can Corporation, and all of them handled hazardous materials. They are underground

storage tanks, the drum storage room, the drum storage pad, the waste solvent tank, and the

hazardous waste storage area. According to available information, no spills have been reported at

the site. A detailed discussion of the SWMUs and wastes managed can be found in section 4.1.

TDD No.: <u>F3-8903-38</u>

National Can Corporation submitted a Part A Hazardous Waste Permit application on November 14, 1980, as required by RCRA. On March 14, 1983, the company asked to withdraw its Part A permit application for a storage facility. Later, after manufacturing operations at the facility ceased, National Can Corporation requested the deletion of its facility as a generator. On July 19, 1984, the Pennsylvania Department of Environmental Resources (PA DER) determined that the subject facility was not a treatment, storage, and disposal (TSD) facility. On May 5, 1989, NUS FIT 3 performed an EPI preliminary assessment of the site. The site visit included a tour of the former National Can Corporation facility and the former SWMU areas and interviews with the site representative.

An estimated 7,860 people live within a 3-mile radius of the site. Seven public water distribution systems supply water, obtained from surface water intakes and groundwater wells, to most of the population within the study area. However, a few residents probably depend on private home wells for their potable water supply.

SECTION 2

TDD No.: <u>F3-8903-38</u>

#### 2.0 THE SITE


#### 2.1 Location

The National Can Corporation site is located in Morrisville, Falls Township, Bucks County, Pennsylvania (see figure 2.1, page 2-2). The facility can be located on the United States Geological Survey (U.S.G.S.) 7.5 minute series Trenton West, Pennsylvania - New Jersey topographic map at 40° 9′ 35″ north latitude and 74° 46′ 7″ west longitude. It can be found on the quadrangle by measuring from the southeastern corner 2-1/2 inches east and 6-1/4 inches north.<sup>1</sup>

#### 2.2 Site Layout

The subject site is located approximately three miles southeast of the Morrisville, Pennsylvania city limits in a large industrial park. Immediately surrounding the property are grassy areas with scattered trees and shrubs. Approximately 300 feet south of the facility is a stone- and gravel-filled area. Formerly, this area south of the facility comprised a grassy, marshy area. A small stream and pondwere also located here. Approximately 400 feet northeast of the on-site building is a pond that covers almost 2/3 acre. The U.S. Steel facility abuts the subject site to the east.<sup>1,2</sup>


Access to the site is easily obtained by using Newford Mill Road, which borders the site to the west (see figure 2.2, page 2-3). Two driveways lead eastwardly from the road approximately 200 feet to a parking lot that is in front of the approximately 31,000-square-foot on-site building. The northernmost driveway continues eastwardly, past the parking lot and parallel to the northern side of the building. It turns to the south at the back, or eastern, side of the building and ends at the former hazardous waste storage area. Some of the front, or western, side of the building is still used for office space. The large central area of the building, which formerly comprised actual sheet metal cutting and coating operations, is now a large warehouse for paper products, china, automobile tires, and carpets. Adjacent to the eastern side of the building is the former hazardous waste storage area. Also on this side of the building, railroad tracks oriented east-west lead from the building's southernmost corner. At the building's southwestern corner is the former pump room, where chemicals were drawn into the building through pipes connected to six underground tanks of raw material; these tanks are located immediately west of and outside the pump room. North of and adjacent to the pump room is a larger room that formerly housed end compound tanks. South of the pump room and projecting from the main building is the former drum storage room. Adjacent to and east of this room is a drum storage pad, and adjacent to and south of the drum storage room is a former drum-receiving dock. South of the drum storage pad is the former location of a waste solvent tank, 1,2,3,4,5



SOURCE: (7.5 MINUTE SERIES) U.S.G.S. TRENTON WEST, N.J. - PA., QUAD

SITE LOCATION MAP NATIONAL CAN CORPORATION SCALE 1: 24000





# SITE SKETCH NATIONAL CAN CORPORATION

(NO SCALE)

FIGURE 2.2



TDD No.: F3-8903-38

Access to the facility is restricted to authorized personnel. A six-foot fence surrounds all but the front of the building.<sup>2</sup>

The site slopes gently to the east. On-site surface water runoff is expected to flow eastwardly to a

grassy area east of the building and then south from the grassy area. 1,2

2.3 Ownership History

U.S. Steel, the current owner of the subject property, has been the owner for an unknown number of

years. Ownership prior to U.S. Steel is unknown. Since 1967, National Can Corporation (now known

as American National Can Company) has been leasing the property from U.S. Steel under a 99-year

lease. In January 1989, American National Can Company subleased the building to Eastern America,

Incorporated, of Philadelphia, Pennsylvania. From 1983 until January 1989, the Raymond Rosen

Company, based in Conshohocken, Pennsylvania, subleased the building. 3,4

Robert Briggs, of Morrisville, Pennsylvania, currently subleases one room in the building. The room

was originally subleased from the Raymond Rosen Company for an unknown number of years. 3.4

2.4 Site Use History

Currently, the on-site building is being used as a warehouse. Since January 1989, Eastern America,

Incorporated, a trucking company based in Philadelphia, Pennsylvania, has used the warehouse to

store Lenox china, various paper products, and automobile tires. Additionally, one room in the

building is used by Robert Briggs, of Morrisville, Pennsylvania. Briggs currently stores carpets in the

room. It is unknown when the storage room was first used by Briggs. From 1983 until January 1989,

the Raymond Rosen Company, an electronics distributor based in Conshohocken, Pennsylvania,

stored televisions and stereo components in the building.<sup>2,4</sup>

From 1967 until 1983, National Can Corporation (now known as American National Can Company)

had full use of the building, which was leased from U.S. Steel. Construction of the building occurred

in 1967. Operations at the facility included the cutting, coating, and painting of sheet metal for the

assembly of cans. Only the assembly of the bottoms of the cans to the sides of the cans was done at

the facility. The incomplete metal cans were shipped off site for final assembly. In 1980 and 1981,

operations were reduced, and, by 1983, American National Can Company had ceased all operations,

operations, were residently and, by 1969, management and account and party management and operations.

moved out of the building, and subsequently subleased the building as a warehouse.<sup>3</sup>

TDD No.: <u>F3-8903-38</u>

#### 2.5 Permit and Regulatory Action History

According to available information, no permits have been issued to the subject facility.3

On August 15, 1980, National Can Corporation filed a Notification of Hazardous Waste Activity, and on November 14, 1980, the Part A Hazardous Waste Permit Application was submitted to EPA (see appendix A for forms).<sup>6,7,8,9</sup> On December 22, 1980, EPA acknowledged these submittals and assigned EPA ID No. PAD046565941 to the company.<sup>10</sup> On July 24, 1981, EPA completed processing the Part A application and determined that National Can Corporation met the requirements for interim status. The hazardous waste codes identified for the facility were F003, F005, F001, D008, and D001. Waste code F017 was temporarily suspended from the list until further determinations of the waste could be made. The process code for the facility was identified as S01.<sup>11</sup>

On March 2, 1983, PA DER made a formal request to the subject facility for its Part B Permit Application. 12 On March 14, 1983, the company informed EPA that it wished to withdraw its Part A Permit Application for a storage facility and remain only a generator. 13 The company also notified PA DER of this, in April 1983. 14 In November 1983, a Notice of Violation was sent to the facility for failure to submit the Part B Permit Application within six months of the request. 15 In April 1984, National Can Corporation again notified PA DER, requesting deletion of its facility as a generator, since all manufacturing operations had ceased in September 1983. 16 On July 19, 1984, it was finally determined by PA DER that the facility was not a TSD facility. A follow-up inspection, also by PA DER, confirmed that hazardous wastes were no longer being generated or stored at the facility. 17 According to available information, no closure plan exists for the facility. 3 See appendix B for permit-related correspondence.

On May 5, 1989, NUS FIT 3 visited the National Can Corporation site to perform an EPI preliminary assessment. The visit included interviews with site representatives and a tour of the facility, including all former SWMUs.<sup>2</sup>

#### 2.6 Remedial Action to Date

No remedial action has been taken at the subject site to date. No spills or releases from the facility are known or have been reported.<sup>3</sup>

SECTION 3

TDD No.: F3-8903-38

#### 3.0 ENVIRONMENTAL SETTING

#### 3.1 Water Supply

Residents within the three-mile radius of the site are served by seven public water supply companies. Some residents are assumed to be utilizing private domestic wells.

The Lower Bucks County Joint Municipal Authority (LBCJMA) serves 86,501 persons in Tullytown Borough and parts of Falls Township and the vicinity, including Levittown. <sup>18</sup> LBCJMA obtains its water from a single surface intake on the Delaware River, located 3.2 miles southwest and downstream of the site near Main Street and Fox Drive in Tullytown, Pennsylvania. Seven groundwater wells, ranging in depth from 40 to 44 feet, lie 100 feet apart in a well field located near Main Street and Fox Drive in Tullytown. These wells are only used in emergencies. <sup>19</sup>

The Township of Falls Authority (TFA) purchases water from LBCJMA to serve approximately 17,500 persons in Falls and Bristol Townships.<sup>20</sup>

The Morrisville Borough Authority (MBA) serves 14,200 persons in Morrisville Borough, Lower Makefield Township, and Falls Township.<sup>21</sup> MBA obtains its water from a single surface intake on the Delaware River, located outside the three-mile radius near Ferry Road and River Road in Morrisville, Pennsylvania.<sup>22</sup> An interconnection with the Pennsylvania - American Water Company (PAWC) currently supplements this system. PAWC serves parts of Lower Makefield and Falls Townships, and all of its water sources are far outside the three-mile radius.<sup>23</sup>

The Trenton Water Works (TWW) serves approximately 220,000 persons in the city of Trenton, most of Hamilton, Ewing, and Lawrence Townships, and part of Hopewell Township. TWW utilizes a surface water intake on the Delaware River, located outside the 3-mile radius of the site, approximately 100 yards north of the Calhoun Street Bridge. TWW has a 104-million-gallon potable water reservoir at Pennington and Prospect Streets in Trenton that is used to store water taken from the Delaware River. TWW also has an emergency interconnection with the Garden State Water Company and the Elizabethtown Water Company.<sup>24</sup>

The Bordentown Water Department (BWD) serves approximately 3,400 persons in Fieldsboro and Bordentown Township and some of Piersonville in Hamilton Township. BWD utilizes three groundwater wells, located far outside the three-mile radius, for its water supply.<sup>25</sup>

TDD No.: F3-8903-38

The Florence Water and Sewer Authority (FWSA) serves approximately 9,975 persons in Florence, New

Jersey. FWSA utilizes four groundwater wells along Summer Street in Florence, located

approximately 3.4 miles south-southeast of the site. These wells are 118 to 130 feet in depth and are

completed in the Raritan Formation.<sup>26</sup>

No local residents utilizing private home wells were identified during the site visit; however, the

nearest residences not supplied with municipal water are located approximately 1-1/2 miles

northwest of the site. 1,2

3.2 Surface Waters

Formerly located south of the site, in an area measuring approximately one mile by 1/4 mile, were

several small ponds, marshy areas, and southward-flowing streams. However, during the site visit, it

was observed that this area has been filled with stone and gravel; some of the area, located farther

south, is now under construction as a landfill.1,2

Currently, the nearest surface water receiving drainage from the site is a three-acre pond located 3/4

mile southeast of the site. A small, unnamed perennial stream flows south-southeastwardly from this

pond approximately 1/2 stream mile before discharging into the Delaware River, which flows

southwestwardly past this confluence, almost two miles from the site. Surface water uses for the

stream and pond are unknown. The Delaware River is used for industrial, drinking water, and

recreational purposes. 1,2,19

The facility lies within the Delaware River's 100-year flood plain. Wetlands greater than five acres in

size that receive drainage from the site are not located within a three-mile radius of the facility. 1.27

Surface water drainage is expected to flow to the east from the site to a grassy area behind (and east

of) the on-site building. From this point, drainage would continue off site in a southward

direction.1.2

The grassy area east of the building is also the location of the facility's on-site septic system. No storm

drains are located on site. 2,3,4

TDD No.: <u>F3-8903-38</u>

#### 3.3 Hydrogeology

The geologic and hydrogeologic conditions in the study area were researched as part of the site investigation. A preliminary literature review was conducted to determine surface and subsurface geologic conditions, soil character, and the status of groundwater transport and storage.

#### 3.3.1 Geology

The National Can Corporation site is located within the Atlantic Coastal Plain Province of southeastern Pennsylvania.<sup>28</sup> The geologic framework of the Coastal Plain consists of underlying, gently southeastward-dipping, unconsolidated marine and fluvial deposits of clay, silt, sand, and gravel of late Cretaceous and Tertiary age. Areas are also covered by interglacial fluvial deposits of Quaternary (Pleistocene) age.<sup>29</sup> In addition, there are exposures of Precambrian age basement rock, primarily in the stream valleys.<sup>30</sup> The study area has a dendritic drainage pattern.<sup>29</sup>

The site is underlain by the Quaternary age Trenton Gravel (see figure 3.1, page 3-4).<sup>30</sup> The Trenton Gravel is a gray to pale reddish-brown, medium- to coarse-grained, very gravelly sand. There are also interbedded clay-silt and crossbedded sand layers.<sup>28,29,31</sup> The formation occurs chiefly and is most continuous in the lowland along the Delaware River from Trenton to the Atlantic Ocean.<sup>29</sup> It is believed to be the equivalent of the Cape May Formation of New Jersey.<sup>31</sup> The youngest of the interglacial formations, the Trenton Gravel has been correlated with the Sangamon interglacial stage (approximately 300,000 years ago). The Trenton Gravel was part of an estuarine-deltaic-marine depositional environment driven and supplied by meltwater and sediment derived from retreating glaciers.<sup>29</sup> Its thickness is approximately 30 to 40 feet.<sup>28,31</sup>



SOURCE: ATLAS OF PRELIMINARY GEOLOGIC QUADRANGLE MAPS OF PENNSYLVANIA

FIGURE 3-1

## GEOLOGIC MAP



TDD No.: F3-8903-38

Although not exposed in the study area, the Cretaceous age Potomac Group and Raritan Formation underlie the Trenton Gravel throughout the study area. These geologic units make up the important Potomac-Raritan-Magothy aquifer, a major water supply source for residents of New Jersey. In the Delaware Valley, Raritan age sediments are indistinguishable from the underlying Potomac Group. The aquifer has been subdivided into the following units: upper clay, upper sand, middle clay, middle sand, lower clay, and lower sand.<sup>32</sup> This nomenclature is equivalent to earlier terminology of upper clay, Old Bridge sand member, middle clay member, Sayreville sand member, lower clay member, and Farrington sand member. Where present, the clay layers function as confining beds (aquitards). Some researchers believe that the Old Bridge sand member should be assigned to the Magothy Formation (a formation that overlies the Raritan Formation in New Jersey). This suggests that the Potomac Group and the Raritan and Magothy Formations would function as one hydrologic unit in the southern Coastal Plain of New Jersey.<sup>33</sup>

The upper clay of the Potomac-Raritan-Magothy aquifer is chiefly a red, white, gray, and yellow clay. It has a maximum thickness of 35 feet; however, it has a limited areal extent. The upper sand is a medium- to coarse- grained sand with minor amounts of very fine- to fine-grained sand. This sand has a thickness of 35 to 55 feet and commonly forms a single, unconfined aquifer with the overlying Trenton Gravel.<sup>28</sup>

The middle clay unit consists of red and white clay and is commonly about 20 feet thick. The middle sand unit is chiefly a brown, yellow, white, and gray, coarse-grained sand and gravel with a maximum thickness of 25 feet.<sup>28</sup>

The lower clay unit consists of brick red and gray clay that is approximately 25 to 40 feet thick. Often when the middle sand unit is absent, the lower and middle clay units merge to form a thick (47 to 60 feet) confining bed. The lower sand unit consists predominantly of coarse-grained sand and fine gravel that grade upward into medium- to fine-grained sand containing a few beds of white clay. The lower sand can range in thickness from 11 to 120 feet.<sup>28,33</sup>

TDD No.: <u>F3-8903-38</u>

Stratigraphically older than the Trenton Gravel and cropping out 0.4 mile northwest of the site are the Pensauken and Bridgeton Formations (undifferentiated).<sup>30</sup> The stratigraphically younger of the two units, the Pensauken Formation is a yellow to dark reddish-brown, extensively crossbedded, cemented sand.<sup>31</sup> It contains interbedded, coarse-grained gravels composed mostly of quartz, quartzite, and chert in addition to pebbles and cobbles of shale, sandstone, and crystalline rocks eroded from Mesozoic to Precambrian age formations.<sup>29,31</sup> The Bridgeton Formation is a yellow, white, or irregularly stained reddish to orange brown, extensively crossbedded, clayey sand. Locally, beds of gravel composed of vein quartz, chert, and quartzite are present.<sup>31</sup> The presence of horizontal gravel beds, crossbedding in the sands, and lenses of gravel suggest a fluvial paleoenvironment for these formations.<sup>29</sup> Both formations have a maximum thickness of 30 feet.<sup>31</sup>

3.3.2 Soils

The majority of the site is underlain by an Urban land - Howell Complex (Uh - 0 to 15 percent slopes) soil. Urban structures cover so much of this land type that identification of the soils is not practical. Most areas have been smoothed, and the original soil material has been disturbed, filled over, or otherwise destroyed by construction. The soil has a slow permeability. Soil pH was too variable to estimate.<sup>34</sup>

The eastern fringe of the site is underlain by Urban land soil. This soil (Ub - zero to eight percent slopes) is so densely covered by urban structures that identification of the soils is not practical. Most areas have been smoothed and the original soil material disturbed, filled over, or otherwise destroyed prior to and during construction.<sup>34</sup>

3.3.3 Groundwater

The Trenton Gravel, the aquifer underlying the site, has a high porosity and a high permeability.<sup>31</sup> In Bucks County, well depths in the Trenton Gravel range from 11 to 102 feet. Static water level ranges from 2 to 23 feet, and well yields range from 10 to 4,000 gallons per minute (gpm). The median well yield for 25 wells is 200 gpm.<sup>28</sup> The Trenton Gravel is hydraulically interconnected to the other sedimentary rock units in the study area because of their relatively similar lithologies and the sporadic continuity of the clay confining layers.

TDD No.: <u>F3-8903-38</u>

The sand units within the Potomac-Raritan-Magothy aquifer have a high porosity and a high permeability. The upper sand forms a hydraulically continuous unit with the Trenton Gravel and therefore functions as a single aquifer (see data on the Trenton Gravel). The middle sand has a yield range of 90 to 775 gpm and a specific capacity range of 2 to 36 gpm per feet. A total of 136 wells in the lower sand have a yield range of 30 to 1,350 gpm and an average yield of 400 gpm. The specific capacity of the lower sand ranges from 4 to 37 gpm per foot.<sup>28</sup>

The direction of shallow groundwater flow is expected to be to the east-northeast, toward the Delaware River, although a component of the flow could also be to the west, toward Van Sciver Lake. Flow direction is based upon topographical observations and the role of rivers as discharge points for groundwater.

#### 3.4 Climate and Meteorology

The climate for the subject area is generally moderate, although extended periods of high temperatures and high humidity are not uncommon during the summer months. The average temperature is 54.8°F. July is the hottest month, with an average temperature of 77.9°F, and December is the coldest month, with an average temperature of 33.2°F. The average yearly precipitation is 41 inches, and the mean annual lake evaporation is 34 inches; therefore, the average net precipitation is 7 inches. A 1-year, 24-hour rainfall will produce nearly 3 inches. 35,36

#### 3.5 Land Use

Land use within the subject area is primarily industrial, although some residential/commercial areas exist nearly 2-1/2 miles west, south, southeast, and north-northeast of the subject facility. The city of Trenton, New Jersey is located three miles northeast of the site. Topography is relatively flat throughout the three-mile radius. The site is located in a large industrial park that comprises nearly the full one-mile radius from the site. A U.S. Steel facility abuts the former National Can Corporation's property to the east and is located up to two miles east and southeast of the subject site. A large landfill, which is currently under construction, can be located approximately 1/2 mile south-southwest of the site. Penn Central Railroad and ConRail tracks intersect the subject area to the east and west of the site. Several state and memorial parks are located two miles southwest and nearly three miles northeast and east of the site. Van Sciver Lake, approximately three miles long by one mile wide (at its widest), is located one to two miles west of the site. 1,2

TDD No.: F3-8903-38

#### 3.6 Population Distribution

An estimated 34 people reside within a 1-mile radius of the subject site. Approximately 840 people live between 1 and 2 miles from the site, and there are approximately 6,986 persons living between 2 and 3 miles from the site. Therefore, there are an estimated 7,860 people living within a 3-mile radius of the site. The most populated areas are several towns located approximately 2.5 miles west, northwest, and southeast of the site. Population figures are based on a count of homes in the subject area multiplied by 3.8 persons per home.1

#### 3.7 Critical Environments

According to the United States Department of the Interior, Fish and Wildlife Service, two federally listed endangered birds are expected to be found as transient species within a three-mile radius of the subject site. These birds include the bald eagle (<u>Haliaeetus leucocephalus</u>) and the peregrine falcon (<u>Falco peregrinus</u>). No listed critical habitat exists for these species within a three-mile radius of the site.<sup>38</sup>

According to the Nature Conservancy, Pennsylvania Natural Diversity Inventory - Eastern Office, three species of plant life that reside within three miles of the subject site have been classified as endangered for the state of Pennsylvania. These plants are the wild ipecac (<u>Euphorbea ipecacuanhae</u>), the Wrights spike rush (<u>Eleocharis obtusa v. peasi</u>), and the long-lobed arrow-head (<u>Sagittaria calycina v. spongiosa</u>).<sup>39</sup>

SECTION 4

TDD No.: F3-8903-38

#### 4.0 WASTE TYPES AND QUANTITIES

The National Can Corporation vacated the property in 1983; since then, hazardous materials have not been generated or stored at the site. Since 1983, the facility has been primarily utilized as a warehouse. From 1967 until 1983, the National Can Corporation operated at the site. In 1980, the National Can Corporation listed the following waste categories as being generated at the facility: F001 (halogenated solvents), F003 and F005 (nonhalogenated solvents), D001 (nonspecified ignitable wastes), and D008 (lead). The above waste codes were derived from the facility's Hazardous Waste Permit Application (Part A), filed in November 1980, and may not completely represent the wastes present at the site. During the NUS site visit, a representative of the National Can Corporation stated that hazardous wastes were generated at the facility during the preparation of metals for coating (degreasers, rags), the cleaning of the coating machinery (paint, vinyls, varnishes, solvents, rags), and the sealing of can ends (solvents). The following solvents were reportedly utilized at the facility: methyl ethyl ketone, methyl isobutyl ketone, hexane, mineral spirits, and toluene. The following materials were observed on the above-ground portions of the on-site underground storage tankst beer body vinyl, beer body primer, and beer end varnish. The chemical constituents and the manufacturing of these materials are currently unknown. 3,7,9

The hazardous wastes generated at the facility were reportedly disposed off site. From 1967 until 1979, the waste disposal practices are not readily documentable, but it was reported that an unknown amount of the wastes were disposed by William Lavelle, of Scranton, Pennsylvania. Mr. Lavelle has been prosecuted for the illegal disposal of hazardous waste at several locations in the Scranton area. From 1979 until 1983, the materials generated at the site were disposed by the licensed hazardous waste disposal firm M & M Chemical, Incorporated, of Andsden, Alabama. The materials were hauled from the site first by National Can Corporation and then by M & M, Incorporated. The materials were reportedly removed from the site every 90 days. Approximately 2 to 3 trucks loads, with eighty 55-gallon drums per load, were reportedly removed every 90 days.<sup>3</sup>

TDD No.: F3-8903-38

4.1 Solid Waste Management Units

Five SWMUs have been identified for the site. The SWMUs were identified by the site representative

during the on-site inspection and from a site plan map prepared by Rollins, Burdick, and Hunter

Company for the National Can Corporation in 1974. The SWMUs may be located on figure 4.1 (page

4-3) and are listed below:3,5

underground storage tanks

drum storage room

drum storage pad

- waste solvent tank

hazardous waste storage area

Specific information concerning the above-listed SWMUs may be found in the following sections.

4.1.1 SWMU No. 1

Underground Storage Tanks

The subject area is located outside the southwestern corner of the facility (see figure 4.1, page 4-3).

The unit consists of 6 underground steel storage tanks (five 8,000-gallon and one 6,000-gallon) that

were utilized to store raw materials used in the can-coating process. All of the tanks have above-

ground tanker truck couplings and discharge outlets within the facility's pump room. The raw liquid

materials, including solvents, primers, and varnishes, were stored in the can and discharged into

drums as needed. The tanks have not been utilized since 1983, and it is not known if any material

remains in the tanks.3,5


Date of Start-Up

The tanks were installed and first utilized in 1967, when the facility became operational.3

Date of Closure

The tanks were reportedly utilized continuously until National Can Corporation vacated the property

in 1983. It is not known if any material remains in the tanks.3



# SOLID WASTE MANAGEMENT UNIT LOCATION MAP NATIONAL CAN CORPORATION

(NO SCALE)





TDD No.: F3-8903-38

Wastes Managed

Waste materials were never stored in the tanks. The tanks were utilized to store mineral spirits,

varnishes, vinyls, and primers. The chemical constituents of the coating materials are unknown.3

Release Controls

The primary containment of the materials consists of five 8,000-gallon and one 6,000-gallon

underground steel tanks.3

There are no known secondary containment features associated with the tanks. The above-ground

features of the tank are located in an unrestricted portion of the site and exist in an unlined gravelly

area adjacent to the facility parking lot.2,3

History of Releases

There are no known or reported releases of hazardous materials from the subject area. Visual

evidence of spillage was observed on the gravel parking lot in the vicinity of the above-ground

couplings. No HNU readings above background were recorded in the subject area.<sup>2,3</sup>

4.1.2 SWMU No. 2

**Drum Storage Room** 

The drum storage room is located within a 25- by 10-foot room that extends from the southwestern

corner of the facility (see figure 4.1, page 4-3). The room is constructed of cinderblocks and has a

cement floor with heavy metal doors on the northern and southern sides. The room was believed to

have been utilized for the storage of 55-gallon drums of raw material. Access to the room was not

gained during the inspection, but the site representative stated that the room is currently subleased

to a carpet contractor for storage.2,3,5

Date of Start-Up

The site representative has no record detailing the use of this area. It is believed that the room was

first utilized for drum storage when the facility became operational in 1967.3

TDD No.: F3-8903-38

Date of Closure

It is believed that the room was utilized for drum storage until the National Can Corporation vacated

the site in 1983.3

Wastes Managed

There is no record detailing the materials stored in the area. It is believed that only raw materials

were stored in the area. The materials that may have been stored in the room are methyl ethyl

ketone, toluene, methyl isobutyl ketone, hexane, and mineral spirits.3

Release Controls

The primary storage of the materials within the room is unknown but most likely consisted of steel

55-gallon drums.

The secondary containment features of the unit are unknown and could not be evaluated in the field.

History of Releases

There have been no known or reported releases of hazardous materials from the subject area. The

subject area could not be visually inspected during the site visit, and HNU readings were not obtained

from the area.2

4.1.3 SWMU No. 3

**Drum Storage Pad** 

The drum storage pad is located adjacent to the eastern side of the drum storage room at the

southwestern corner of the facility (see figure 4.1, page 4-3). The unit consists of an open-air, 25- by

10-foot concrete platform. The unit is bordered by the building on two sides and by unpaved grassy

areas on the remaining sides. According to photographs taken in November 1980, the platform and

the grassy area east of the platform were used for the storage of 55-gallon steel drums (see appendix

C for photographs). The site representative has no record of the area's utilization as a drum storage

area.2,3,5,37

TDD No.: F3-8903-38

Date of Start-Up

It is believed that the area was first utilized for drum storage when the facility opened in 1967.3

Date of Closure

It is believed that the area was continually utilized for drum storage until the facility closed in 1983.3

Wastes Managed

There is no record detailing the materials stored in the area. It is not known if raw materials, waste

materials, or empty drums were stored in the area.3

Release Controls

If raw or waste liquid materials were stored in the area, the primary containment of the materials

would have consisted of 55-gallon steel drums. The drums were stored on steel racks and directly on

the concrete pad. The unbermed concrete pad is bounded on the west and north by the facility walls

and on the east and south by unpaved grassy areas. All surface drainage from the pad will flow

toward the grassy areas.2

History of Releases

There are no known or reported releases of hazardous materials from the subject area. Visual

evidence of spillage (oil-stained soil) was observed along the edge of the concrete pad. No HNU

readings above background were recorded in the subject area.2

4.1.4 SWMU No. 4

Waste Solvent Tank

The waste solvent tank is believed to have been located directly south of the drum storage pad (see

figure 4.1, page 4-3). The tank was not present during the NUS site visit, and the site representative

had no information concerning the tank or its usage.<sup>3,5</sup>

TDD No.: F3-8903-38

Date of Start-Up

It is believed that the tank was installed and first utilized in 1967, when the facility began

operations.3

Date of Closure

It is believed that the tank was continually utilized until 1983, when National Can Corporation

vacated the property.3

Wastes Managed

The materials stored in the tank are unknown but, based on its name, it can be assumed that waste

solvents were deposited into the tank. The solvents known to have been utilized at the facility

include methyl ethyl ketone, toluene, methyl isobutyl ketone, hexane, and mineral spirits. Based on

the known solvents utilized at the facility, the following waste categories were potentially stored in

the tank: F001, F003, and F005.2,3,5

Release Controls

The primary containment of the waste solvents consisted of the tank. The specifics of the tank (size,

construction, etc.) are unknown. The secondary containment of the materials is unknown, but the

area where the tank is believed to have been located is an unpaved grassy area with no observable

diversionary or containment features. 2,5

**History of Releases** 

There are no known or reported releases of hazardous materials from the subject area. No HNU

readings above background were recorded in the subject area.<sup>2</sup>

TDD No.: F3-8903-38

4.1.5 SWMU No. 5

**Hazardous Waste Storage Area** 

The hazardous waste storage area is located outside the eastern side of the facility and adjacent to

the northern wall of the railroad car loading docks (see figure 4.1, page 4-3). The unit consists of a

paved, open area that was designed for the storage of hazardous materials that were generated in

the facility. The materials were reportedly stored in 55-gallon drums and on wooden pallets and

were routinely removed from the site for disposal.<sup>2,3,5</sup>

Date of Start-Up

The subject area was reportedly first utilized in 1967 when the facility became operational.3

Date of Closure

The subject area was reportedly utilized for hazardous storage until the National Can Corporation

vacated the site in 1983.3

Wastes Managed

All of the hazardous wastes that were generated at the facility were reportedly stored in the subject

area. Based on the materials known to have been utilized at the facility, the following wastes are

believed to have been present in the subject area: methyl ethyl ketone, toluene, methyl isobutyl

ketone, hexane, mineral spirits, unknown vinyls, primers, and varnishes, solvent rags, waste oils, and

other miscellaneous materials. Based on RCRA permit application, the following waste categories

were generated by the facility and are believed to have been stored in the area: F001, F003, F005,

D001, and D008.3,7,8

Release Controls

The primary containment of the materials stored in the area consisted of 55-gallon drums.<sup>3</sup>

**History of Releases** 

There are no known releases of hazardous materials from the subject site. No HNU readings above

background were recorded in the subject area.<sup>2,3</sup>

SECTION 5

TDD No.: F3-8903-38

#### 5.0 FIELD TRIP REPORT

#### 5.1 Summary

On Friday, May 5, 1989, NUS FIT 3 members Donna McKeever and Carl Rodzewich conducted an EPI preliminary assessment of National Can Corporation. The FIT was accompanied by Judith Peters, senior environmental specialist for American National Can Company, and Herb Massaro, of Eastern America, Incorporated. Weather conditions at the time of the site visit were rainy and overcast, with temperatures in the mid-50s. Photographs were obtained at the site by FIT 3 members (see figure 5.1, page 5-4, and the photograph log, section 5.4).

#### 5.2 Persons Contacted

#### 5.2.1 Prior to Field Trip

Joseph Kotlinsky U.S. EPA 841 Chestnut Building Ninth and Chestnut Streets Philadelphia, PA 19107 (215) 597-8392

Judith Peters
Senior Environmental Specialist
American National Can Company
8770 West Bryn Mawr Avenue
Chicago, IL 60631-3504
(312) 399-3162

Herb Massaro Eastern America, Incorporated 8501 Hegerman Street Philadelphia, PA 19136 (215) 333-4444 R.M. Rivetna Manager, Environmental Engineering American National Can Company 8770 West Bryn Mawr Avenue Chicago, IL 60631-3504 (312) 399-3392

Sharon O'Keef Dickinson, Wright, Moon, Van Dusen and Freeman 800 First National Building Detroit, MI 48226 (313) 223-3614

James Harper
William Walsh
U.S. EPA
841 Chestnut Building
Ninth and Chestnut Streets
Philadelphia, PA 19107
(215) 597-0823
(215) 597-1192

TDD No.: F3-8903-38

#### 5.2.2 At the Site

Judith Peters
Senior Environmental Specialist
American National Can Company
8770 West Bryn Mawr Avenue
Chicago, IL 60631-3504
(312) 399-3162

Herb Massaro Eastern America, Incorporated 8501 Hegerman Street Philadelphia, PA 19136 (215) 333-4444

#### 5.2.3 Water Supply Well Information

During the EPI preliminary assessment, no home wells in the subject area were located. However, the nearest residences not supplied with municipal water are located approximately 1-1/2 miles northwest of the site.

TDD No.: <u>F3-8903-38</u>

#### 5.3 Site Observations

• The HNU was set on the 0-to-20 setting; no readings above background were recorded.

• The mini-alert was set at the X1 position; no readings above background were recorded.

• The site is approximately 16-1/2 acres in size.

• Five SWMUs are associated with the site: underground storage tanks, the drum storage room, the drum storage pad, the waste solvent tank, and the hazardous waste storage area.

• Surface water runoff is expected to flow to the east from the site, onto a grassy area, and

then southwardly.

Access to the property and the on-site building was unrestricted; one room that is used to

store carpets was locked.

• The National Can Company facility is no longer used for its original purposes. The on-site

building was used solely as a warehouse at the time of the FIT visit.

• The underground raw storage tanks associated with National Can Corporation were intact; it

could not be determined whether they contained chemicals.

APPENDIX A

	Please print or type with ELITE type "? characters/inch) in the unshaded areas only.	GSA No. 024	6-EPA-OT		
	ROTTER VIEW OF HAZARDOUS WASTE ACTIVITY	METRUCTIONS:	lf vou receis	-1	ي. د د د د د د د د د د د د د د د د د د د
		label, affix it in the	he spece at le	ft. If any	of the
			A STATE OF THE STA	inform	n tion
	I. STALLATION TO				ne il
		William Composers but	Trems. Theta	filation" m	mens 8
	II. MAILING PLEASE PLACE LABEL IN THIS SPACE	single site where treated, stored br	d/or disposed	EA de a	trana
	。	porter's printings to the INSTRUCT	TONS FOR F	TLING NO	OTIFI
	LOCATION	CATION Before Information reque	sted herein is	required:i	by Jaw
	A IGES. Enter the feath called number from 48 OFR Fath 35 and car has been an arranged and	Section 3010 of the Recovery April 360	HABITS FR	ZUSOGII AT	EVIII 3
¥	the soft them is seed of necessity.	med application of	94 245 M	receive of	3-0
TAC	FOR OFFICIAL USE ONLY COMMENTS	ACRA	SECTION		
ADE		<b>同学</b> AFE	GION ILI		
	INSTALLATION'S EPA I.D. NUMBER APPROVED DATE RECEIVED	HEITE	ann ic		
	FPADO 4656594121 2008-8			F.U	) 4
	I. NAME OF INSTALLATION	A CONTRACTOR	,	16- 1	A
4	NATIONAL CAN CORPORATION				
	II. INSTALLATION MAILING ADDRESS	Salar Modern	STATE AND IN	e days	<b>FO</b>
	STREET OR P.O. BOX 1				
	3 NEWFORD MILL ROAD				
		CODE			
	4MORRISVILLE PAIG	067	The state of the s		Park Taran
	III. LOCATION OF INSTALLATION	1 11 11 11 11			
	STREET OR ROUTE NUMBER				
		77 art ru <sup>2</sup> n5 3310			
	CITY OR TOWN STYLE ZIP	CODE 11 CARACTER 1	er en	20 May 100	- 1: 
	6 MORRISVILLE PH 190	067	:		
	IV. INSTALLATION CONTACT  NAME AND TITLE (lost, first, & job fifte) 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PHONE NO	(area code & n		
	Sherrape DAT DO AUT MANAGED	21/5/20	75101		64 (2) . 17.14
	V. OWNERSHIP	45 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	31 34	<u>~1</u>	
4	A. NAME OF INSTALLATION'S LEGAL OWNER	明本政治 11	****		
ACH	8NATIONAL CAN CORPORATION				
DET	(enter the appropriate arter into box) VE TYPE OF HAZARDOUS WASTE ACTIVITY (enter the appropriate arter into box)	ter "X" in the ap	propriate bo	x(es))	
4	F = FEDERAL	RANSPORTATION	l (complete its	m VII)	
	I ME - NON EEDERAL [7/1]	NDERGROUND II	HECTION		
	VII. MODE OF TRANSPORTATION (transporters only - enter "X" in the appropriate bo	ox(es))			
	A. AIR S. RAIL S.C. HIGHWAY D. WATER SE COTHER	(apecify):		·	
	VIII. FIRST OR SUBSEQUENT NOTIFICATION  Mark "X" in the appropriate box to indicate whether this is your installation's first notification of hazar	rdous weste activity	or a subsecu	ent natific	ation.
	If this is not your first notification, enter your Installation's EPA I.D. Number in the space provided bel		,	3	
		C. INST	ALLATION'S	S EPA I.D.	NO.
	A. FIRST NOTIFICATION B. SUBSEQUENT NOTIFICATION (complete item	C)			
	IX. DESCRIPTION OF HAZARDOUS WASTES  Please go to the reverse of this form and provide the requested information.				

THE THE BEES OF THE COURT OF TH	rs/inc/r).			w/m/ -1)	Form Approved OMB No. 1	58-A0	175	پارل سر نستون
I FORM I			INFORM	AATION	I, EPA I,D. NUMBER			T/AL C
GENERAL SEPA (Read	Сопа	olida	ted Permits F		FPADO4656		<u> </u>	<b>       </b>
I. EPA I.D. NUMBER		/			GENERAL INSTR If a preprinted label has b it in the designated space.	een p Revien	rovide w the	inform-
III. FACILITY NAME					ation carefully; if any of i through it and enter the appropriate fill—in area be	correctiow. A	t dat Viso, i	s in the
FACILITY V. MAILING ADDRESS PLEASE	PI AC	FI	AREL IN	THIS SPACE	the preprinted data is absorber of the label space litthat should appearly, pleas	iti the	info	omation
A THE ASE	1		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		proper fill—in area(s) belong complete and correct, you litems 1, III, V, and VI	need	not o	ereigmos
VI. FACILITY					must be completed regard items if no label has been the instructions for detu	<i>iless).</i> provid	Com ded.	piete all Refer to
					tions and for the legal a which this data is collected.	uthori		
II. POLLUTANT CHARACTERISTICS								
INSTRUCTIONS: Complete A through J to determ questions, you must submit this form and the supp if the supplemental form is attached. If you answer is excluded from permit requirements; see Section C	lemental ''no'' to	forn sac struc	n listed in the housestion, yetions. See als	e parenthesis following the qui ou need not submit any of the	istion. Mark "X" in the box in se forms. You may answer "no	the th	ird et Dùr ac	olumn ctivity
SPECIFIC QUESTIONS			O FORM		DUESTIONS	YES	ă	ATTACKE
A. Is this facility a publicity owned treatment which results in a discharge to waters of the (FORM 2A)	U.S.?		X	- Include a concentrated	(either existing or proposed) animal feeding operation or on facility which results in a U.S.7 (FORM 2B)		X	21
C. Is this a facility which currently results in disch to waters of the U.S. other than those describ	narges ed in	)	<b>C</b>		y (other than those described will result in a discharge to M 2D)	- 29	У 24	17
A or B above? (FORM 2C)  E. Does or will this facility treat, store, or disponent to the control of the control	ose of	X	×	F. Do you or will you inject municipal effluent below taining, within one qui	or at this facility industrial or the lowermost stratum con- arter mile of the well bore, trinking water? (FORM 4)	31	X	. 23
G. Do you or will you inject at this facility any proc water or other fluids which are brought to the su	duced urface	28	29 30	H. Do you or will you injec	at at this facility fluids for spe- tining of sulfur by the Frasch	21	<u>ν</u> χ	13
in connection with conventional oil or natural ga duction, inject fluids used for enhanced recove oil or natural gas, or inject fluids for storage of hydrocarbons? (FORM 4)	ry of liquid	7	ζ 35 36	process, solution mining	of minerals, in situ combus- covery of geothermal energy?	37	^   ^	39
<ol> <li>Is this facility a proposed stationary source who one of the 28 industrial categories listed in the structions and which will potentially emit 100</li> </ol>	he in-			NOT one of the 28 ind instructions and which	ed stationary source which is ustrial categories listed in the will potentially emit 250 tons		×	
per year of any air pollutant regulated under Clean Air Act and may affect or be located attainment area? (FORM 5)	in an		X   42		tant regulated under the Clean or be located in an attainment	43		45
III. NAME OF FACILITY								
SKIPNATIONAL CAN	COR	OP	ORAT			5.0		
IV. FACILITY CONTACT	last, first	, & ti	itle)		. PHONE (area code & no.)		2,	
DETTORRE PATRIC	K /	2 د	ANT	MGR 21	5 295 8/2/			
V. FACILITY MAILING ADDRESS  A. STREET OF	R P.O. BI	o x	940 J. A.F.		Africa de parte (1965)			4.
3 NEWFORD MILL RO	AD.	···	! i i !	45				
4 MORRISVILLE		1		C.STATE D. ZIPCO	T			
VI. FACILITY LOCATION	1.00		18 (18 18 18 18 18 18 18 18 18 18 18 18 18 1				٠	
	AD	ECIF	IC IDENTIF	ER				
B. COUNTY NAME		. 1		•				
LOWER BUCKS	, , , ,		- 1 <del>1 1.</del>	70				
6 MORRISVILLE	1 1		<del> </del>	PA 1901	PE F. COUNTY CODE			-
07/022/37/222			<del> </del>					

EPA Form 3510-3 (6-30)

SOI

3

1

600

7

8

9

10

Contin NOTE					2. is page before completing if	ıav	e me	ore	than	26	wasi	tes t	o lis	rt.					Form Approved OMB No. 158-S80004
-	ΕPA	Γ		· · · · ·	BER (enter from page 1)			, ,	b				F	OR (	OFF	FIC	1 A L	USE	E ONLY
WF	A	P	<u> </u>	<u>'</u>	6565941	/ /		/	W	ż				D١	•				2 DUP
ĪV.	7				N OF HAZARDOUS WAST		(CO)		iuec	1)			ć (*)					V	D. PROCESSES
LINE NO.	I H	A.E AZI AST aser	E N cod	0	B. ESTIMATED ANNUAL QUANTITY OF WASTE	,   0	F M E SUR 'ente code	EA- E					(er	SS (					2. PROCESS DESCRIPTION (if a code is not entered in D(1))
<u> </u>	F	0		7	<del>"-414</del>	-	Ŧ		\$7 <b>\$</b> 7	۔ ا ر	9 2 	<del></del>	29	27	· · ·	29	27	120	SUSPENDED 1/16/81 F.R.
2	F	0	0	3		_							,				,	<del></del>	included with above
3	F	0	0	5						,-									included with above
4	F	0	0	1	25		7		S	0		1		,			'	'	
5	D	0	Ì	ì	130		T		S	01			·		, , , , , , , , , , , , , , , , , , ,				
6	D	0	إص	!	130	_	7		5	<u>,</u>		<u>'</u>		<u> </u>	' 		· '		·
7									,	•			•		·				
8				i						ı		ı	1		'		,	•	
9									<u> </u>			1	Г		- 1		ſ	ı	· ·
10			•									. ['	T	,			Ţ		
11										1"		τ	Τ	'	1		'		
12		1										1	·		,				
13									1	1		1	1		Ŧ		1	1	
14									ł	ı		1						,	
15	1			-						1 -		I			ı		ı	-Т	
16												Т						7	
17												7"	1				· . r		
18										,		'	1		1			1	
19										1		1			1				
20		_								1		1			1			, -	
21										Ţ		T			7			7	
22		-										ĺ							
23													1	, "				1	
24										T		T			1		Т		
25									T	ı		1			- 1			1	
26	1 33	Ţ		-9 -3	, la		75		27	- 22	) } }	1	29	2.7		29	27	- 19	9
EPA I	5 ~~~	. 75	10.3	16	201														CONTINUE ON DEVEN

APPENDIX B



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

#### REGION III

### 6TH AND WALNUT STREETS PHILADELPHIA, PENNSYLVANIA 19106

JUL 2 4 1981:

Mr. N. Chernikoff National Can Corporation Newford Mill Road Morrisville, PA 19067

Dear Mr. Chernikoff:

This is to acknowledge that the Environmental Protection Agency has completed processing the information submitted in your Part A Hazardous Waste Permit Application. It is the Agency's opinion, based on the assumption that the information submitted is complete and accurate, you as an owner or operator of a hazardous waste management facility have met the requirements of Section 3005(e) of the Resource Conservation and Recovery Act (RCRA) for Interim Status. EPA has not verified the information submitted. If it is determined that the information is incomplete or inaccurate, you may be asked to provide additional information or in certain circumstances it may be determined that you do not qualify for interim status. In addition, this notice does not preclude a citizen from taking legal action under the provisions of Section 7002 of RCRA.

A facility not meeting the requirements for interim status under Section 3005 of RCRA may be required to close until such time as a hazardous waste permit is issued. Interim status may also be terminated, according to procedures in 40 CFR Part 124, if the owner or operator fails to furnish additional information which EPA requests in order to process a permit application.

As an owner or operator of a hazardous waste management facility, you are required to comply with the interim status standards as prescribed in 40 CFR Parts 122 and 265 or with State rules and regulations in those States which have been authorized under Section 3006 of RCRA. In addition, you are reminded that operating under interim status does not relieve you from the need to comply with all applicable State and local requirements.

The enclosure to this letter identifies the processes your facility may use, their design capacities, and types of waste your facility may accept during interim status. This information was obtained from the Part A Permit Application. If you wish to handle new wastes, change processes, increase the design capacity of existing processes, or change ownership or operational control of the facility, you may do so only as provided in 40 CFR Sections 122.22 and 122.23.

#### HAZARDOUS WASTE INSPECTION REPORT Generators - Part A

• Me	form John
Date of inspection 5/3/84 Time start	
Name of inspector GARY BONNER	
Company, installation name NATIONAL CAN CORPORATION	
Location NEW FORD MILL RD	
County BUCKS Municipality FALLS 74	ρP :
Identification number PAD 046 565 941	• • • •
Name of responsible official R. M. RIUETNA	<u> </u>
Title MANAGER ENUIRONMENTAL ENGINEERING	
Mailing address 8/01 HIGGINS RD, CHICAGO, ILCINOIS	
Area code and phone no. (3/2) 399-3392	
Name of person interviewed	
Title	•
Tailing address (if different from above)	
Area code and phone no.	
1. Current waste handling method: $\mathcal{N}/\!$	
a. 🖊 On-site 🖊 treatment, 🦳 storage, 🖊 disposal	
b On-site use, reuse, recycle, reclaim	
c Off-site treatment, storage, / disposal	<b>-</b>
d.   Off-site   use,   reuse,   recycle,   reclaim	
2. Amount of hazardous waste produced:	
a kg./mo.	A
b kg./yr.	NATIONAL CAN CORP.
3. Types of hazardous waste produced by Hazardous Waste Number.	JUN 111984
3. Types of hazardous waste produced by Hazardous Waste Number:	0011 1 1984
Pons	ENVIRONMENTAL ENGINEERING

## HAZATTOUS WASTE INSPECTION REPORT Part C - Comments

ate of Inspection	5/2/24	Identification Number PAD 046 565 941
_		CAN CORPORATION
ounty Bucks	· · · · · · · · · · · · · · · · · · ·	Municipality FALCS 7WP
	•	
_		THAT HAZARDOUS WASTES ARE NO LONGER
GENERATED O	R STORED AT	THE FACILITY. SECTION 75.267 (b) (7)
REQUIRES THA	I A REUISED	NOTIFICATION FORM BE SUBMITTED
WHEN HAZARDO	ous waste is	NO LONGER GENERATED. THE FORM WAS
PREVIOUSLY PR	BUIDED TO YOU	1. IF YOU HAVE ANY QUESTIONS PLEASE
CONTACT ME		· · · · · · · · · · · · · · · · · · ·
· · · · · · · · · · · · · · · · · · ·		
:		
: -		
his inspection report invironmental Resource	is official noti	fication that a representative of the Department of d Waste Management, inspected the above installation.
	uspection are show	WM 10 fbig renowe - Americal and an actual
he results of laborat	ory analyses and	iolations may also be discovered upon examination of review of Department records. Notification will be indicated herein and listing any additional violations.
Inspector (stonetura)	A R	Date 0/4/84
· (o+Sudcare)	Jung Don	Date 6/4/84

If you have any questions concerning this letter, please write to the address shown or call Bill Walsh at 215/597-1230.

Sincerely yours,

Shirley D. Bulkin

Chief, Administrative Support Section

Permit Enforcement Branch

Enclosure

Date Prepared: July 24, 1981

The information shown below is based solely on the information that the owner and operator of this facility submitted in Part A of the Hazardous Waste Permit Application. This is not a determination by EPA that this facility is an environmentally acceptable facility for treating, storing or disposing of the hazardous wastes listed below.

1. Facility name, location, and EPA Identification Number.

Name: National Can Corporation

Location: Newford Mill Road

Morrisville, PA 19067

EPA I.D. No.: PAD 04 656 5941

II. EPA considers the following to be the owner or operator of the facility and therefore the person(s) who must comply with the requirements set forth in 40 CFR Parts 122 and 265.

Owner's Name: Mr. N. Chernikoff

Operator's Name:

III. During the period of interim status, the facility may use only the following processes for treating, storing or disposing of hazardous waste, up to the design capacities that are indicated.

PROCESS	DESIGN CAPACITY
S01	15,600 Gals.
	**************************************
<del></del>	<del></del>

IV. During the period of interim status, the facility may handle only the hazardous wastes with the following EPA Hazardous Waste Numbers, and/or solid waste exhibiting hazardous characteristics with the following EPA Hazardous Waste Numbers.

F003 F005 F001 D008 D001

<sup>\*</sup> For Waste Code F017, See Attachments

#### ATTACHMENT

Re: Paint Wastes

EPA has completed its initial review of your application to treat/store/dispose of hazardous waste under the Resource Conservation and Recovery Act (RCRA). The paint wastes listed as being handled by your facility have been temporarily suspended from regulation as a listed hazardous waste. An amendment to 40 CFR Part 261.32, Hazardous Waste from Specific Sources, was published in the Federal Register on January 16, 1981. This amendment temporarily suspended the listing of all wastes from the manufacture of paints (EPA Hazardous Wastes Nos. F017, F018, K078, K079, K081, K082) until further study on those wastes has been conducted. However, wastes which exhibit any of the hazardous waste characteristics (i.e. reactivity, ignitability, corrosivity, and EP toxicity) as defined in 40 CFR Part 261 remain subject to regulation under RCRA.

EPA requests that you make a determination as to whether or not the waste streams listed on your application are hazardous by one or more of the general characteristics. Ignitability and EP toxicity would be the characteristics which would most likely cause paint manufacturing wastes and residues to be defined as a hazardous waste. In order to properly process your permit application and avoid further inquiries, a response within 10 days would be beneficial to yourself and EPA.

If you have any questions, please do not hesitate to contact Bill Walsh at (215) 597-1230.

All replies should be addressed to:

U.S. Environmental Protection Agency Permits Enforcement Branch RCRA Administrative Support Section 6th and Walnut Streets Philadelphia, PA 19106 Attn: Ms. Shirley D. Bulkin (3EN24)



# COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES 1875 New Hope Street Norristown, PA 19401 215 631-2420



March 2, 1983

Mr. Patrick Dettorre, Plant Manager National Can Corporation New Ford Mill Road Morrisville, PA 19067

Re: EPA Identification No. PAD 046565941

Facility Name:

National Can Corporation

New Ford Mill Road

Falls Township, PA 19067

Dear Mr. Dettorre:

This letter constitutes a formal request for Part B of your application for Hazardous Waste Management Facility Permit under the Hazardous Waste Management Regulations, 25 PA Code Chapter 75, Subchapter D, for the facility referred above. This request is made under the authority of Section 75.265(z)(6) of the regulations. You should refer to the hazardous waste management regulations that appeared in the Pennsylvania Bulletin dated September 4, 1982, which was recently mailed to you for the requirements of the Part B application. Your Part B application must be submitted no later than September 1, 1983. If there is information that is being claimed as confidential, indicate this according to the requirements of Section 75.265(z)(16).

If your facility is not a TSD (treatment, storage or disposal site), or if you stopped functioning as a TSD facility after November 19, 1980, or if you qualify under the Permit by Rule provision of the regulations, it will be necessary for you to contact one of our field offices, and to arrange for an inspection to confirm this. Our field offices and the areas covered are the Bethlehem Office, phone number 861-2070, covering Berks, Lehigh and Northampton Counties; and the Norristown Office, phone number 631-2420, covering Philadelphia, Bucks, Chester, Delaware and Montgomery Counties.

If you functioned as a TSD after November 19, 1980, it will be necessary for you to submit four copies of a closure plan to Mr. Bruce Beitler of this office.

Enclosed are reference checklists for your Part B application that are to be used to insure your application contains the minimum information required. These checklists are to be used to assist you in your Part B application and our subsequent review, although the checklists are not a substitute for reviewing and addressing the hazardous waste regulations themselves. Because you may be anticipating additional facilities at your location, we have included checklists for every type of facility covered by the Department requirements. Please use only those checklists that apply to the types of facilities for which you are making application.

Your Part B application will be reviewed for a hazardous waste management TSD Permit by both the U. S. Environmental Protection Agency and the Department of Environmental Resources until the Commonwealth of Pennsylvania receives Phase II Interim Authorization under the RCRA Program to solely administer a permitting program.

You should submit the Part B application to both agencies for their concurrent review. This would require that the hazardous waste requirements under Pennsylvania regulations as well as the hazardous waste management requirements under the Federal program would have to be addressed.

When completed, please transmit your application and five copies (or seven copies if there is an incineration facility) to our office, and if you have any questions or desire to have a pre-application conference, please contact Mr. Lawrence H. Lunsk, Solid Waste Facilities Supervisor, at the letterhead address, or by calling 215 631-2420.

Very truly yours,

WAYNE L. LYNN Regional Solid Waste Manager

Re P770

**ENCLOSURE** 

400°



April 27, 1983

Pennsylvania Department of Environmental Resources Bureau of Solid Waste Management P. O. Box 2063 Harrisburg, PA 17120 Attn: Ms. Gayle Leader

RE: NOTIFICATION OF HAZARDOUS WASTE ACTIVITY
REQUEST FOR A CHANGE IN STATUS
DELETION OF STORAGE ACTIVITY
NATIONAL CAN CORPORATION
FAIRLESS HILLS FACILITY
U.S. EPA IDENTIFICATION NUMBER PAD046565941

#### Dear Ms. Leader:

Attached please find the completed Notification of Hazardous Waste Activity Form which you sent us April 15, 1983. This form indicates deletion of our facility as a storage facility but retains our generator status. We are hereby requesting deletion of the storage activity for our Fairless Hills facility.

As stated in our March 14, 1983 letter to Ms. Shirley Bulkin of US EPA Region III, copy attached, our Fairless Hills facility has never stored hazardous waste longer than the 90 day limitation and we do not anticipate storage over the 90 day limit in the future. We, therefore, have determined that a hazardous waste permit for this facility is no longer required.

At the present time this facility is a small quantity generator. We do, however, wish to retain our US EPA Identification Number should we have hazardous waste to ship off-site in the future.

We trust the supplied information is sufficient to delete the storage activity for this facility and retain our generator status.

Pennsylvania Department of Environmental Resources Attn: Ms. Gayle Leader

If you have any questions or require additional information do not hesitate to contact the undersigned at (312) 399-3392.

Yours very truly,

NATIONAL CAN CORPORATION

R. M. Rivetna

Manager

Environmental Engineering

RR/gs attachment

cc: Mr. Larry Lunsk
Commonwealth of Pennsylvania
Dept. of Environmental Resources
1875 New Hope Street
Norristown, PA 19401

bcc: J. Peters - EXEC

J. Sampson - ENGR

G. Cohen - FAIR



#### CERTIFIED

March 14, 1983

Ms. Shirley D. Bulkin
Environmental Protection
Specialist
RCRA Permit & Pesticides
Section
Waste Management Branch
U.S. EPA Region III
6th and Walnut Streets
Philadelphia, PA 19106

RE: WITHDRAWAL OF HAZARDOUS WASTE
PERMIT PART A APPLICATION
NATIONAL CAN CORPORATION
FAIRLESS HILLS FACILITY
U.S. EPA IDENTIFICATION NUMBER PAD046565941

#### Dear Ms. Bulkin:

On November 14, 1980, National Can Corporation submitted a Hazardous Waste Permit Part A Application for the above plant to be a storage facility. This Permit Part A Application for a storage facility was submitted so that this plant could store hazardous waste in the event that the hazardous waste could not be moved off-site within the 90 day limitation. Since this Hazardous Waste Permit Part A was submitted, we have not stored any hazardous waste over the 90 day limitation at this plant and we do not anticipate storage over the 90 day limit in the future.

We have, therefore, determined that a hazardous waste permit for this plant as a storage facility is no longer required and we wish to withdraw our Hazardous Waste Permit Part A Application as a storage facility for this plant. We do, however, wish to retain our generator status and all hazardous waste will continue to be moved off-site within the 90 day limitation.

We trust this information is sufficient to withdraw our Hazardous Waste Permit Part A.

Ms. Shirley D. Bulkin March 14, 1983 Page 2

If you have any questions or require additional information do not hesitate to contact the undersigned at (312) 399-3392.

Yours very truly,

NATIONAL CAN CORPORATION

R. M. Rivetna

Manager

Environmental Engineering

RR/gs

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

N. Chernikoff

cc: Mr. Gary R. Galida
Chief, Division of
Hazardous Waste Management
Bureau of Solid Waste
Management
Commonwealth of Pennsylvania
Department of Environmental
Resources
P. O. Box 2063
Harrisburg, PA 17120

AHOOMI C

#### BUREAU OF SOLID WASTE MANAGEMENT NOTIFICATION OF HAZARDOUS WASTE ACTIVITY

R-SWM-53: Rev. 3/82	della grande	and the same	Contract to the second	7. V. W. T.	A STATE OF THE STA	25.50
INSTALLATION'S EPA I.D. NUMBER	THE PROPERTY OF					
1ADD4656594V			•			dilitar ber
NAME OF INSTALLATION	CHAIR S					46.4
National Can Corporation	V					
II INSTALLATION MAILING ADDRESS		<b>建筑等等</b>	中部外理等	<b>建筑建筑</b>	SCHOOL SCHOOL	いったで
STREET OR P. O. BOX				· ·	·	
Newford Mill Moad	·	· · · · · · · · · · · · · · · · · · ·		ST.	ZIP CODE	
	······································	,		PA	19067	-
Morrisville	L'A TANDOTAN COSTA	HOLES IN THE STATE OF	waste Ab Edi	2652		1
IV LOCATION OF INSTALLATION				MUNICIP	ALITY	<u> </u>
STREET OR ROUTE NUMBER			Falls			
SAME		<u> </u>	Pall			
CITY OR TOWN	ST.	ZIP CODE		coul		
			1	ower	Bucks	
V. INSTALLATION CONTACT		and the same of	24日本中		A PERSON	<b>6</b> 阿子也
MAME AND TITLE (last, first, & job ti	idel			PHO	NE NO. farse cod	e & no.)
Cohen, George Plant Mana	aner	<del></del> -		2/1/5	129518	1/12
Cohen, George Flam man	Constant Con		1	141.4		建安徽
VI. OWNERSHIP	TALLATION	S LEGAL OWNE	<b>1</b> *			
		······································				
NATIONAL CAN CORPORA	110N	<del></del>	-			
B. TYPE OF OWNERSHIP		and the second	in the second se			
(enter the appropriate letter into box)		ingk india				J 10
F - FEDERAL M - NON-FEDERAL				in the state of th		
VII SIC CODES (4-digit in order of priority)				THE		
A, FIRST	-		C. TH	RD		
I (specify) on I I A		(specify)				-·.
314111 = 11/ETAT CU113	of one on the		0, FC	URTH		
		(specify)	الباكنداده بدير يستحدنوني	فالأسترش ومستور بيسي		
(specify)	Control District	in the same of the same of the	The state of the s	in The second	SKQM^+4F4	B-A-S
VIIL DIPE OF HAZARDOUS WASTE ACTIVITY					RECYCLE, REGL	
	C THOMPL			A STATE OF		
B. TREAT	F. PERMIT	SY RULE		L OTHER	specify):	
IX MODE OF TRANSPORTATION (transporters only)	STATE OF		Archive L	-	A ME COM	
A. AIR & S. RAIL- C. HIGHWAY	D. WATER	- T. OTH	En (specify):			
						1, 14
A. NPDES (Discharges to Surface Water) D. PSD (Air Emission			100	er.		<del>•</del>
			1.0			-
		<del></del>		ا مانس		<i>,</i> · · ·
B. UIC (Underground Injection of Fluids) E. SC	OLID WASTE			.4.46		•
			<u>., </u>			
C. RCRA (Hazardous Wastes) F.	OTHER		: lapacif	14:25	,,	
		Property and	() 李小士			1.00
XI. TYPE OF NOTIFICATION,	• • • • • • • • • • • • • • • • • • • •			re greivier	or notification of	change
Mark "X" in appropriate box to indicate whether this is your instead information, hazardous waste handled, of hazardous waste actions in the second s	stallation's fire stivity, if you	x notation of check 8, C, D, E	or F, sttach	a letter of e	xplanation (SEE	INSTRU
HONSI.			Ø	E. DELET	ION OF AN ACTI	VITY
	ETION OF A			F. ADDIT	ION OF AN ACTI	٧١٢٢
THE HEIMANGE OF GENERAL INFORMATION (4) OF ADD						

XII DESCRIPTION OF HAZARDOUS WASTES (Continued from front)	
A HAZARDOUS WASTES FROM NON-SPECIFIC SOURCES, Enter the	four-digit number from \$75.261(h)(2), for each fisted hexardous wests
from non-specific sources your installetion handles. Use additional shee	
Fobs Foos III	
7 8 9	10 11 12
B. HAZARDOUS WASTES FROM SPECIFIC SOURCES. Enter the four-c	init number from \$75,261(h)(3) each listed hazardous waste from specific
industrial sources your installation handles. Use additional sheets if neces	ary.
13 14 15	16 17 18
10 29 21	23 24 24 24
25 25 27	28 29 30
C. COMMERCIAL CHEMICAL PRODUCT HAZARDOUS WASTES. Enter your installation handles which may be a hazardous weste. Use additions	the four-digit number from \$75.261(h)(4) for each chemical substance if necessary.
31 32 33	34 35 36
37 38 39	40 41 42
43 44 45	46 47 48
D. CHARACTERISTICS OF NON-LISTED HAZARDOUS WASTES. Men. hazardous westes your installation handles. (See: \$75,261(g) (2) through	(151) I was to see the second of the second
1_IGNITABLE ≥ CORROSIVE	3. REACTIVE A EP TONIC
XIII CERTIFICATION	
	ed and am familiar with the information submitted in this and all individuals immediately responsible for obtaining the information, and complete. I am aware that there are significant penalties for the and imprisonment.
SIGNATURE   NAME	and OFFICIAL TITLE (Type or Print)  OATE SIGNED
Trucho Man	ager-Environmental Engr.
FOR OFFICIAL USE ONLY	

#### Department of Environmental Resources

1875 New Hope Street Norristown, PA 19401 215 631-2420

November 17, 1983

Mr. Patrick Dettorre, Plant Manager National Can Corporation New Ford Mill Road Norrisville, PA 19067

#### NOTICE OF VIOLATION

Re: Application No. PADO46565941

Dear Ir. Dettorre:

In a letter dated March 3, 1983, the Department of Environmental Resources made a formal request for your Part B application for a hazardous waste management facility permit. This application was required to be submitted to the Department no later than September 1, 1983, which was six months after the date of the request. Since you have not submitted the Part B application within the required time, you are in violation of the Department's hazardous waste facility regulations as set forth in 25 Pa. Code Section 75.265(z)(6).

Within 14 days please submit to the Department your Part B application for your bazardous waste management facility permit or explain your reasons for believing that your facility is not subject to the requirements of Section 75.265(z)(6). If you are no longer functioning as a hazardous waste treatment storage or disposal facility you will have to submit a revised notification form indicating your change in status. Upon receipt of this information confirmation will be under by our staff. Contact Mr. James Dolan at 631-2420 to obtain these forms.

Very truly yours,

LAWRENCE H. LÜNSK Solid Waste Facilities Supervisor

cc: Field Supervisor • Re 30 LP37

MAR 1 1984



April 11, 1984

Mr. Gary Bonner
Pennsylvania Department of
Environmental Resources
Bureau of Solid Waste Management
PO Box 2063
Harrisburg, PA 17120

Dear Mr. Bonner:

RE: Notification of Deletion of Generator Status National Can Corporation - Fairless Facility USEPA ID No. PADO46565941

Enclosed is the Notification of Hazardous Waste Activity form which indicates our request to delete the generator status of this facility.

National Can Corporation discontinued manufacturing operations at the Fairless facility in September, 1983. At the present time, we do not anticipate resuming operations at this facility and therefore request deletion of our status as a generator of hazardous waste.

We trust the supplied information is sufficient to delete this facility as a generator of hazardous waste.

If you have any questions or require additional information, do not hesitate to contact the undersigned at (312)399-3392.

Very truly yours,

NATIONAL CAN CORPORATION

R. M. Rivetna

Manager

Environmental Engineering

RMR/et

bcc: J. Peters - EXEC J. Sampson - "

8789C

enclosures

### BUP TOF SOLIO WASTE MANAGEMENT

ರ ಕರ್ಮಾರ್ಭಾಗಿಗಳು ಆಕ್ರಾಕ್ಷಾಗ್ರವೀಕರ್ ರ್ವ ಧರ್ಮನಾವುಗರ್ಗಾಡುವುದ ರಾಜಕಾಗಿ ಸಾಹಿತ್ಯಗಳು

WM-53: R-v. 3-52 NOTIFICALLON OF HAZA	ARDOUS WASTE ACTIVITY
MOTALLATION'S EPAID NUMBER	
100465659411	
NAME OF INSTAULATION	
NATIONAL CAN CORPOR	RATION
おみなしし、おかれなみにいる 2003 650	
5TREIT OR 7, G. 30X	
8101 West Higgins Roan	
CITY OR TOWN	ST. \ 214 CDDE
Thicago.	TL 60631
LOGATION OF INSTALLATION	
STREET OR ROUTE RUNGER	MUNICIPALITY
NEWFORD MILL ROAD	FALLS -
מאסד הפיצונים	ST. ZIP CODE COUNTY
MORRISVILLE	PA 19067 LOWER BUCKS
INSTALLATION CONTACT	
HANK 1893 ਵਾਵਿਤ ( <i>la</i> n, first, å job tid:	PHOME NO. farm code & no.)
RIVETNA, ROHINTON-MG	gr. ENV. ENGR 3/2/3/9/3/3/9/
I OWNERS - P	
A. NAME OF THEFT	ALLATION TILEGAL DWY 8TH
NATIONAL CAN CORPOR.	ATION
B. TYPE OF OWNERSHIP	
(אתפר נהוי אונים (אתפר יחוד (אתפר המויקס) אוני אוני אוני אונים (אתפר יחוד (אונים אונים אונים אונים אונים אונים	
AFREDERAL IA - NO HAR DER NA MANAGER NA MANA	
1 II SIC CODED (4-wait in case of priority)  A. FIRST	C.THRO
	(secity)
14 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	D. FOURTH
(	
	TRANSPORTATION G. REUTE, RECYCLE, RECLAIM
	COMPLETE ITEM IXY
D. TREAT D. DIMPOSE 7	F. PERMIT BY BULZ
(vino <del>concessed</del> ) (O'TATROGENA ST RO EDDM XI	
A. AIR	D. WATER Z. OTHER (meetly):
Z EXIDERS HARBORS JATHER OF THE CHITCHE IN	
A. MPDES (Discreptes to Surface) Whiteh   17. D. PSD (Air Emissions &	तंत्रज्ञ Proposed Spuress
S. UIC (Unda-round to estion of Fluids) E. SQL	10 WASTE
CO. RORA His suddons Watesh F. O.	OTHER (mrsty)
777 07 107 107 107 107 107 107 107 107 1	
YPE OF MOTIFICATION	
, General information, nazardous wasta handled, or hazardous wasta attivi	:"stion's first notification of hamroaus waste activity, or notification of a change ਸਨਾ, ਪਿ you check B, C, D, E, or ਜੋ, attach a letter of explanation (355 ਪਿਤਾਸਿਪ
TIONS).  A. FIRST NOTIFICATION  C. DELET	FIGH OF A WASTE SET BELETION OF AN ACTIVITY
	TION OF A WASTE F. ADDITION OF AN ACTIVITY

XII DESCRIPTION OF HAZAROQUS MASTES (Communed from immed	
A HAZAROOUS WASTES FROM NON-SPECIFIC'SQURCES, Error the four-sight number from non-tracific sources your inculiation bandes. Use additional shorts if necessary.	from 575.231(b)(2) for each listed hetargous harmy
1 2 3 4 F00B F00B 110 110 110	3 5   5   11   12   12   13   13   13   13   13
B: সAZAROOUS YASTES FROM SPECIFIC SOURCES. ইনাল the four-clight number from 9 hidustrial sources your inequilation handles. Use additional pheno if necessary.	75.281(b)(3) each listed hamrdous wasta from specific in the control of the contr
13 14 15 16 16 17 17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18	23 12 29 29 20
CL_COMMERCIAL CHEMICAL PRODUCT HAZARDOUGNAUTES. Sent the four-digitation of the four-digitation of the sent to the four-ways of the beat to the sent	
37     32     8     24       37     23     22     40       43     45     45	25 35 35 35 35 35 35 35 35 35 35 35 35 35
್ನ ರಚಿಸಿಗಿ ಎರಡು ಸಾಗೀತ ರೂ. ಸರಚ್ಚಿಟರ್ 20 ನೀಡಿ ನಿರಾಧ ಉಪ್ಪುಗತ್ತು, ಗಿರ್ವೇ ಗಳಿಗಳ ಸಂಪಡಿಸಿ ಕಾರಣ ಸ್ಥಾನಿಕ್ಕಾರ (57) ್ಲಿ 'ಶಿಸಲು ಗೆರಂತ ಸಾಗೀತ your installation handles, (See 575.031(5)(3) ಮೇಗಾಲ್ಯೂ (57)	errapouding to the frameworks. At con-listed
1. IGNITABLE 2. CORRESIVE 3	ב אנדטגום 🔀 4. פאדטגום
XIII GERTIFICATION	
l cartify under panelty of law that I have personally examined and any familia attorned documents, and that based on my inquiry of those individuals immed I believe that the scientised information is true, accurate, and complete. I submitting take information, including the possibility of fine and imprisonn	distally responsible for obtaining the information, am aware that there are significant penalties for
SIGNATURE OF A COLOR O	LE (Type or Print)  DATE SIGNED  21 Ironmental Engl. 4.12.84
FOR OFFICIAL USE ONLY	ironmental only





## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES

1875 New Hope Street Norristown, PA 19401 215 270-1920



July 19, 1984

Mr. R. M. Rivetna, Manager Environmental Engineering National Can Corporation 8101 West Higgins Road Chicago, IL 60631

Re: Fairless Facility

Identification No. PAD046565941

Dear Mr. Rivetna:

It has been determined by our staff that you are not a TSD facility or that you qualify under the permit by rule provision in our hazardous waste management rules and regulations.

Therefore, you will not have to submit a Part B hazardous waste permit application and we are returning your Part A application if you previously submitted one to the Department.

This means you no longer have interim status as a TSD facility and you may not engage in this type of activity at your facility. You will not be required to secure a hazardous waste management permit for your facility, but you are still subject to any portion of the hazardous waste management rules and regulations published in the Pennsylvania Bulletin September 4, 1982 which pertain to your facility. This includes the submission of a closure plan if you operated as a treatment storage or disposal facility after November 19, 1980.

If you qualify under the permit by rule provision of the regulations then you may continue to operate as a hazardous waste facility in accordance with NPDES or local sewer authority requirements.

This does not release you from Environmental Protection Agency requirements. You will have to contact their Philadelphia Regional Office to verify that you do not have to submit a Part B application to their agency.

If you have any questions concerning this, I can be reached at the above number.

Very truly yours,

LAWRENCE H. LUNSK

Solid Waste Facilities Supervisor

NATIONAL CAN CORP.

cc: Falls Township
Bucks County Health Department

Division of Hazardous Waste Management

U.S. EPA Code 3AW32


Re 30 4W 201


JUL 23 1984


ENVIRONMENTAL FNGINFFRING


APPENDIX C

Tational Can Corpration Fairless Drum Storage ARea November, 180










# PHOTO LOCATION MAP NATIONAL CAN CORPORATION (NO SCALE)

FIGURE 5.2





Photos #1, #2, #3, #4
Pan of former facility facing
northeast





Photo #5
Former hazardous waste storage area facing southwest



Photos #6, #7 Pan of former pump room (now tire storage) facing southwest

1 1




Photo #8 Shot of former end compound tanks room facing northwest




Photo #9 Close-up of location of underground storage tanks facing northeast

F3-8903-38

## POTENTIAL HAZARDOUS WASTE SITE

	ENTIFIC	
01 ST	ATE 02 SI	TE NUMBER
P/	A l	2454

PART	PRELIMINAR 1 SITE INFORMA - I			SENT P	A	2454		
II. SITE NAME AND LOCATION		····.		<del></del>	<del></del>			
01 SITE NAME (Legal, common, or descriptive name of site)		02 STREE	T. ROUTE NO., O	R SPECIFIC LOCATION IDENTI	FIER		<del></del>	
National Can Corporation	Newford Mill Road							
03 CITY			05 ZIP CODE	06 COUNTY		07COUNTY	108 CONG	
Morrisville		D.	10057			CODE	DIST	
	NGITUDE	PA	19067	Bucks		017	PA08	
40°_09'_35"_N74°_4	16' 07". W							
10 DIRECTIONS TO SITE (Starting from nearest pubble road) Travel east on the Pennsylvania Turnpi	ike to exit 29.	Trave	el north or	n Route 13 approxi	matelv	2-1/4 m	iles.	
Make a right, go over a bridge, and o	continue to the	first	traffic li	oht. Turn left o	nto Bri	istol Pi	ke.	
At the fork in the road, bear right or	ito Bordentown	Road.	Cross Van	Sciver Lake: make	a leff	t onto N	ewford	
III. RESPONSIBLE PARTIES Mill Road.	he site is 1/4	mile a	ahead on th	ne rìght.				
01 OWNER (# known)			T (Business, mailing,					
I C Charl Comments			•	·				
U.S. Steel Corporation	·	DA STATE	Triess Hil	1s Industrial Par				
Manual 2017		1		( 215) 736-420:				
Morrisville 07 OPERATOR (It known and different from owner)		PΑ	19067		<u> </u>			
Of OPERATOR (II Known and different from owner)		08 STREE	T (Business, mailing, i	residential)		•		
Eastern America, Incorporated			01 Hegerma	n Street		-		
09 CITY	•	10 STATE	11 ZIP CODE	12 TELEPHONE NUMBE	R			
Philadelphia		PA	19136	(215) 333-444	4			
13 TYPE OF OWNERSHIP (Check one)		•	·	· · · · · · · · · · · · · · · · · · ·	<u></u>			
X A. PRIVATE C B. FEDERAL:	(Agency name)		_ □ C. STAT	E D.COUNTY D	E. MUNÍCI	IPAL		
☐ F. OTHER:Specif			_ □ G. UNKI	NOWN				
14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply)	y)			<del></del>				
X A RCRA 3001 DATE RECEIVED: 11 / 14/80 MONTH DAY YEAR	☐ B. UNCONTROLL	ED WASTE	E SITE (CERCLA 10	Jei DATE RECEIVED:	TH DAY Y	EAR I C	NONE	
IV. CHARACTERIZATION OF POTENTIAL HAZARD						·		
	eck af (hat apply)	CONTRA	oron C					
LA LEGI DALE O / O / OO	LOCAL HEALTH OFFI		F. OTHER:	C. STATE D. O	HER CON	NTRACTOR		
= 11O	RACTOR NAME(S):	11110	Corporatio	n. FIT 3 (Specify)				
02 SITE STATUS (Check one)	03 YEARS OF OPER			.,, ., .				
□ A. ACTIVE ಔ B. INACTIVE □ C. UNKNOWN	00 12/1/10 01 01 2/10	1967	198	3 D UNK	NOWN			
·	В	EGINNING YE			HOWN			
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN								
Solvents including methyl ethyl ketone	, methyl isobu	tyl ket	one, hexan	e, mineral spirits	, tolu	ene, and	i	
unknown vinyls, primers, varnishes, an	d oils.							
				•				
05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND	OR POPULATION	·-·			<del></del>			
There is possible groundwater contamin	ation from und	ergroun	d storage	tanks, which are o	urrent	lv intac	t.	
Ituis unknown whether they contain mat	erials, but ev	idence	of spillage	e was observed dur	ina th	e site v	icit	
				- 110 0000,700 00,	1119 011	C 3100 Y	1310.	
V. PRIORITY ASSESSMENT			· <del>- · · ·</del>					
01 PRIORITY FOR INSPECTION (Check one. If high or medium is checked.	complete Part 2 - Waste Inform	nation and Pari	3 - Description of Ha	Zardous Conditions and increants)				
☐ A. HIGH ☐ B. MEDIUM (Inspection required promptly)	(Inspect on time		C D. NON		disposition lo	orm)		
VI. INFORMATION AVAILABLE FROM						<del> </del>		
01 CONTACT	02 OF (Agency/Organiza	elion)			03 T	ELEPHONE !	NUMBER	
Paul : Racette	U.S. EPA				(2	15) 597-	1073	
04 PERSON RESPONSIBLE FOR ASSESSMENT	05 AGENCY	08 ORGA	NIZATION	07 TELEPHONE NUMBE	B OBT	DATE		
					1	_	, 89	
Donna McKeever	NUS	FIT	3	(215) 687-9510	J   -	WONTH DAY		

## **\$EPA**

# POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

ı.	IDEN1	RECATION
11	STATE	02 SITE NUMBER
	PA	2454

II. HAZARDOUS CONDITIONS AND INCIDENTS
01 X A GROUNDWATER CONTAMINATION 02 OBSERVED (DATE: ) X POTENTIAL ALLEGED 03 POPULATION POTENTIALLY AFFECTED: approx. 756/3 104 NARRATIVE DESCRIPTION
There is the possibility for groundwater contamination if underground storage tanks, which are currently
intact, contain materials and are leaking. Stained soil was observed at several locations at the site.
intact, contain materials and are leaking. Stained soil was observed at several locations at the site. As no municipal wells are located within three miles of the subject site, the population on groundwater was determined by a house count of areas not serviced by a public water supplier and multiplying that number by 3.8 (persons per home).
01 T B. SURFACE WATER CONTAMINATION 02 TO OBSERVED (DATE:) TO POTENTIAL TO ALLEGED 03 POPULATION POTENTIALLY AFFECTED: 34/1 miles 04 NARRATIVE DESCRIPTION
Wastes handled by National Can Corporation were removed by 1983; however, signs of spillage were observed
during the site visit. The nearest surface water that receives drainage from the site is located 3/4 mile
south-southeast of the site.
01 C. CONTAMINATION OF AIR 02 C OBSERVED (DATE) C POTENTIAL CALLEGED 03 POPULATION POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION
None known or reported; wastes handled by National Can Corporation were removed by 1983.
Horse known of reported y master as sy that even our series will be remoted by 1200.
01 X D FIRE EXPLOSIVE CONDITIONS 02 OBSERVED (DATE:)
There is a possible hazard if underground storage tanks still contain materials and are disturbed and
exposed to fire or explosive conditions.
01 X E. DIRECT CONTACT 02 \(\text{OBSERVED}\) (DATE: \(\text{DATE}\) \(\text{X}\) POTENTIAL \(\text{DALLEGED}\)
03 POPULATION POTENTIALLY AFFECTED: < 50 O4 NARRATIVE DESCRIPTION
Signs of spillage at the underground storage area and the drum storage pad were observed during the site
visit. It is unknown whether materials are still contained in underground tanks. Access is unrestricted
in these areas.
01 X F CONTAMINATION OF SOIL 02 COBSERVED (DATE: ) X POTENTIAL CALLEGED 04 NARRATIVE DESCRIPTION
Signs of spillage at the underground storage area and the drum storage pad were observed during the site
visit. It is unknown whether materials are still contained in underground tanks or if tanks are leaking.
visit. It is unknown whether materials are still contained in anderground tanks of it tanks are reaking.
01 X G. DRINKING WATER CONTAMINATION 756/3 02 D OBSERVED (DATE:) X POTENTIAL . ALLEGED
03 POPULATION POTENTIALLY AFFECTED: approx. 756/3 04 NARRATIVE DESCRIPTION miles
The nearest residential area not supplied with municipal water is located 1-1/2 miles northwest of the site
There is a possibility of groundwater contamination if underground storage tanks, which are currently
intact, contain materials and are leaking. Stained soil was observed at several locations at the site.  Population on groundwater was determined as mentioned above (A).
01 X H. WORKER EXPOSURE/INJURY 02 □ OBSERVED (DATE:)
Signs of spillage at the underground storage area and the drum storage pad were observed during the site
visit. It is unknown whether materials are still in underground tanks or if the tanks are leaking.
Access to these areas is unrestricted.
01 % I. POPULATION EXPOSURE/INJURY 02 © OBSERVED (DATE:)
The population potentially affected includes those using groundwater and surface water, workers at the site
trespassers to the site, and those people having direct contact with a contaminated area.
and the state and the state people having allow delivers a convenience and

## **\$EPA**

#### POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 2 - WASTE INFORMATION

I. IDENTIFICATION					
01 STATE	02 SITE NUMBER				
PA	2454				

Messures of wester quantities   Messures of wester quantities   Messure partities	II. WASTE STATES, QUANTITIES, AND CHARACTERISTICS								
A SOLOGE O GAS  CALCY VARIABLE  TO OTHER THE SECRET OR OF PROPERTY OF THE STREET OF TH	O1 PHYSICAL ST	ATES - Check all that apply)	02 WASTE QUANTI	2 WASTE QUANTITY AT SITE		O3 WASTE CHARACTERISTICS (Check all Inat apply)			
TO STANDONGTON STANDARD STANDA	- 4 SOUD	TE SHIRRY		vaebeudeut)			LE CILHIGHLY V	OLATILE	
UNIXASTETYPE  CATEGORY SUBSTANCENNME OLGROSS AMOUNT OF UNIT OF MEASURE OF COMMENTS  SLU SLUDGE UNKNOWN 1983. It is unknown whether six  SOL SOLVENTS > 25 tons/yr, underground storage tanks still contain materials. Naste amounts are taken from the Part A Permit Application.  INCO INCORGANIC CHEMICALS 130 tons/yr, from the Part A Permit Application.  INCO INCORGANIC CHEMICALS 130 tons/yr.  INCOR		PEINES XELICIAID	TONS _	unknown			/E		
IN MASTETYPE  CATEGORY SUBSTANCE NAME O: GROSS AMOUNT O ZUNTOF MEASURE OS COMMÉNTS  SUU SUDGE UNKNOWN APIL 1983. It is unknown whether six D. 1985. It is unknown unknow	Ă C SLUDGE	. G GAS	CUBIC YARDS _	unknown		ENT X H. IGNITAI	BLE L. INCOMP M. NOT AP		
SUBSTANCE NAME	_ O OTHER	(Specify)	NO. OF DRUMS _	unknown					
SLU SLUDGE Unknown All waste was removed from the site by OLW OILY WASTE Unknown   1983. It is unknown whether six   SOL SOLVENTS > 25 tons/yr   underground storage tanks still contain materials. Waste amounts are taken materials. Waste amounts are taken in the part A Permit Application.  OCC OTHER ORGANIC CHEMICALS   130 tons/yr.   from the Part A Permit Application.  OCC MORGANIC CHEMICALS   130 tons/yr.   from the Part A Permit Application.  OCC ACIDS   130 tons/yr.   from the Part A Permit Application.  W. HAZARDOUS SUBSTANCEN ROME   02 CAS NUMBER   04 STORAGE DISPOSAL METHOD   OS CONCENTRATION   OS MEASURES CONCENTRATION   OUTSIDE drum storage / tank   Unknown   Unkn	III. WASTE T	YPE							
OLW OLLY WASTE unknown 1983. It is unknown whether six  SOL SOLVENTS > 25 tons/yr. underground storage tanks still contain PSD PESTICIDES  OCC OTHER ORGANIC CHEMICALS 130 tons/yr. from the Part A Permit Application.  IOC INORGANIC CHEMICALS 130 tons/yr.  IOC INORGANIC CHEMICALS 130 tons/yr.  IOC INORGANIC CHEMICALS 130 tons/yr.  IV. HAZARDOUS SUBSTANCES: Gereaceant in most requirement of the CAST in members of	CATEGORY	SUBSTANC	E NAME	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMÉNTS			
SOL SOLVENTS > 25 tons/yr. underground storage tanks still contain PSO PESTICIDES   materials, Naste amounts are taken OCC OTHER ORGANIC CHEMICALS   130 tons/yr. from the Part A Permit Application. IOC INORGANIC CHEMICALS   130 tons/yr.  ACD ACIDS   MARKET   MARKE	SLU	SLUDGE		unknown		All waste wa	s removed from	the site by	
PSD PESTICIDES   materials Naste amounts are taken   OCC OTHERORANIC CHEMICALS   130   tons/yr.   from the Part A Permit Application.   IOC   NORGANIC CHEMICALS	OLW	OILY WASTE		un known		1983. It is	unknown whether six		
OCC OTHERORGANIC CHEMICALS 130 tons/yr. From the Part A Permit Application.  IOC INDRGANIC CHEMICALS	SOL	SOLVENTS		> 25	tons/yr.	underground storage tanks still contain			
INORGANIC CHEMICALS	PSD	PESTICIDES				materials.	Waste amounts a	re taken	
ACD ACIDS BAS BASES MES HEAVY METALS 130 tons/yr.  WHAZARDOUS SUBSTANCES (SEA ADDRAWN NOTWORK PROMOBILITY PROMOBIL	occ	OTHER ORGANIC	CHEMICALS	130	tons/yr.	from the Part A Permit Application.		ication.	
BAS BASES MES HEAVY METALS 130 tons/yr.  IV. HAZARDOUS SUBSTANCES 154 ACCOUNT INTEREST MEDIANIN CONTROL 157 ACCOUNT MEDIANIN CONTROL	юс	INORGANIC CHE	MICALS				·		
MES HEAVY METALS 130 tons/yr.  IV. HAZARDOUS SUBSTANCES (500 ARGERING FOR MACE MODERN)  IV. HAZARDOUS SUBSTANCES (500 ARGERING FOR MACE MODERN)  OI CATEGORY 02 SUBSTANCE MAME 03 CAS NUMBER 04 STORAGE DSPOSAL METHOD 05 CONCENTRATION CONCENTRATION  SOL methyl ethyl ketone unknown butside drum storage/ tank unknown unknown  SOL hexane unknown outside drum storage/ tank unknown unknown  SOL toluene 108-88-3 outside drum storage/ tank unknown unknown  MES lead 7433-92-1 outside drum storage/ tank unknown unknown  SOL mineral spirits unknown outside drum storage unknown unknown  INROWN UNKNOWN UNKNOWN  SOL mineral spirits unknown outside drum storage unknown unknown  INROWN UNKNOWN  INROWN OUTSIDE drum storage unknown unknown  INROWN OUTSIDE drum storage unknown unknown  INROWN OUTSIDE drum storage unknown unknown  INROWN	ACD	ACIDS							
IV. HAZARDOUS SUBSTANCES   See Appendix Formact Integration   Color	BAS	8ASES							
OCATEGORY OZ SUBSTANCE NAME OZ CAS NUMBER OLAS SUBSTANCE NAME OZ CAS NUMBER OLAS SUBSTANCE NAME OZ CAS NUMBER OLAS SUBSTANCE NAME OZ CAS NUMBER FDS			·		tons/yr.				
SOL methyl thyl ketone unknown butside drum storage/ tank unknown unknown unknown butside drum storage/ tank unknown unknown unknown butside drum storage/ tank unknown unknow	IV. HAZARDO	OUS SUBSTANCES (S	Appendix for most frequen	ly ciled CAS Numbers)				- LOGIAE ARUBE OF	
SOL methyl isobutyl ketone unknown butside drum storage/ tank unknown unknown SOL hexane unknown outside drum storage/ tank unknown unknown SOL toluene 108-88-3 outside drum storage/ tank unknown unknown MES lead 7439-92-1 outside drum storage unknown unknown SOL mineral spirits unknown outside drum storage unknown unknown SOL mineral spirits unknown outside drum storage unknown unknown SOL mineral spirits unknown outside drum storage unknown unknown SOL mineral spirits unknown outside drum storage unknown SOL mineral spirits unknown unknown SOL mineral spirits unknown outside drum storage/ tank unknown unknown SOL mineral spirits unknown SOL mineral spirits unknown unknown SOL mineral spirits SOL	O1 CATEGORY	02 SUBSTANC	E NAME	03 CAS NUMBER	04 STORAGE/DISF	POSAL METHOD	05 CONCENTRATION	CONCENTRATION	
SOL	SOL	methyl ethy	ketone	unknown	putside drum s	torage/ tank	unknown	unknown	
Toluene   108-88-3   Outside drum storage   tank   Unknown   Unk	SOL	methyl isob	ityl ketone	unknown	putside drum s	torage/ tank	unknown	unknown	
MES   lead	SOL	hexane		unknown	outside drum :	storage/ tank	unknown	unknown	
SOL	SOL	toluene		108-88-3	outside drum	storage/ tank	unknown	unknown	
V. FEEDSTOCKS See *Locandar for CAS Numbers)  CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER FDS Same materials as above FDS	MES	lead		7439-92-1	outside drum	storage	unknown	unknown	
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS	SOL :	mineral spir	rits	unknown	outside drum	storage	unknown	unknown	
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS									
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS								ļ	
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS									
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS								ļ	
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS									
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS									
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS						· ···			
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS					<b></b>			ļ	
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS									
CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER CATEGORY 01 FEEDSTOCK NAME 02 CAS NUMBER  FDS same materials as above FDS FDS  FDS FDS FDS FDS FDS									
FDS	V. FEEDSTO	OCKS See 4 opendix for CAS A	umbers)						
FDS	CATEGORY	01 FEEDSTOCK NAME		02 CAS NUMBER	CATEGORY	01 FEEDSTOCK NAME 02 CAS NU		02 CAS NUMBER	
FDS         FDS           FDS         FDS           FDS         FDS	FDS	same materia	ils as above		FDS				
FDS FDS	FDS				FDS				
	FDS				FDS				
VI. SOURCES OF INFORMATION (Cite specific references, e.g., state Mes. sample analysis, reports )	FDS				FDS				
	VI. SOURCE	S OF INFORMATION	(Cite specific references, e.g	., state liles, semple analysis,	reports )			<del></del>	

NUS FIT 3. Preliminary assessment; site visit. TDD No. F3-8903-38, May 5, 1989.

**SEPA** 

## POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT ART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENT

I. IDENTIFICATION
01 STATE 02 SITE NUMBER
PA 2454

	FHAZARDOUS CONDITIONS AND INCIDENTS	PA	2454
II. HAZARDOUS CONDITIONS AND INCIDENTS (Cantinued)			
01 ☐ J. DAMAGE TO FLORA 04 NARRATIVE DESCRIPTION	02 () OBSERVED (DATE:)	□ POTENTIAL	☐ ALLEGED
None reported or observed.			
01 E.K. DAMAGE TO FAUNA 04 NARRATIVE DESCRIPTION (Include name(s) of species)	02 D OBSERVED (DATE:)	D POTENTIAL	□ ALLEGED
None reported or observed.			
01 □ L. CONTAMINATION OF FOOD CHAIN 04 NARRATIVE DESCRIPTION	02 G OBSERVED (DATE:}	□ POTÉNTIAL	☐ ALLEGED
None reported or observed.			
01 X M. UNSTABLE CONTAINMENT OF WASTES  Spails funcil standing hourds leaking drums)  03 POPULATION POTENTIALLY AFFECTED: 7,860/3 miles and the standing hours and the standing hours are standing to the standing hours and the standing hours are standing to the standing hours are standing hours.	02 G OBSERVED (DATE:)  1es 04 NARRATIVE DESCRIPTION	(X POTENTIAL	□ ALLEGED
It is unknown whether underground storage are leaking. No secondary containment ex handled at some former storage locations	tanks, which are currently intact, s ists for the tanks. Specifics about are unknown. Stained soils were obser	till contain n containment a cved in two of	materials or nd materials these areas.
01 ☐ N. DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:)		C ALLEGED
None reported or observed.	·		
01 TO. CONTAMINATION OF SEWERS, STORM DRAINS, WY 04 NARRATIVE DESCRIPTION	WTPs 02 C OBSERVED (DATE:)	☐ POTENTIAL	□ ALLEGED
No storm drains were observed during the leasee of the building.	site visit. An on-site septic system	is used by t	he current
01 _ P ILLEGAL/UNAUTHORIZED DUMPING 04 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:)	☐ POTENTIAL	☐ ALLEGED
None reported or observed.			
06 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR A	ALLEGED HAZARDS		
None reported or observed.			
III. TOTAL POPULATION POTENTIALLY AFFECTED: _7	,860 within 3 miles		
IV. COMMENTS			
V. SOURCES OF INFORMATION (Cite specific references, e.g. state	e liles, sample analysis, reports)		
NUS FIT 3. Preliminary assessment; site United States Geological Survey. Trenton Topographic Map. 1955, photorevise	West, Pennsylvania - New Jersey Quad		inute Series.

SECTION 6

TDD No.: F3-8903-38

#### 6.0 REFERENCES FOR SECTIONS 1.0 THROUGH 5.0

United States Geological Survey. Trenton West, Pennsylvania - New Jersey Quadrangle, 7.5
Minute Series. <u>Topographic Map.</u> 1955, photorevised 1970. Combined with Trenton East,
Pennsylvania - New Jersey Quadrangle, 7.5 Minute Series. <u>Topographic Map.</u> 1957,
photorevised 1981; Bristol, Pennsylvania - New Jersey Quadrangle, 7.5 Minute Series.
<u>Topographic Map.</u> 1955, photorevised 1981; and Columbus, New Jersey Quadrangle, 7.5
Minute Series. <u>Topographic Map.</u> 1957, photorevised 1981.

- 2. NUS Corporation, FIT 3. Preliminary assessment; site visit. TDD No. F3-8903-38, May 5, 1989.
- 3. Peters, Judith, American National Can Company, with Donna McKeever and Carl Rodzewich, NUS FIT 3. Meeting. May 5, 1989.
- Massaro, Herb, Eastern America, Incorporated, with Donna McKeever and Carl Rodzewich, NUS FIT 3. Meeting. May 5, 1989.
- 5. Rollins Burdick Hunter Company Engineering Service. National Can Corporation Facility Map, Plant No. 39, Morrisville, Pennsylvania. April 1974.
- 6. Rivetna, R.M. National Can Corporation, to the United States Environmental Protection Agency (Region III). Correspondence. August 15, 1980.
- 7. United States Environmental Protection Agency. Notification of Hazardous Waste Activity. Environmental Protection Agency Form 8700-12 (6-80). August 4, 1980.
- 8. Rivetna, R.M. National Can Corporation, to the United States Environmental Protection Agency (Region III). Correspondence. August 15, 1980.
- 9. United States Environmental Protection Agency. Hazardous Waste Permit Application, Part A. Form 3510-3(6-80). November 14, 1980.
- United States Environmental Protection Agency, to Patrick Dettorre, National Can Corporation. Acknowledgment of Application for a Hazardous Waste Permit. December 22, 1980.

TDD No.: F3-8903-38

Bulkin, Shirley D., United States Environmental Protection Agency, to N. Chernickoff, National Can Corporation. Correspondence. July 24, 1981.

- 12. Lynn, Wayne L., Pennsylvania Department of Environmental Resources, to Patrick Dettorre, National Can Corporation. Correspondence. March 2, 1983.
- 13. Rivetna, R.M., National Can Corporation, to Shirley D. Bulkin, United States Environmental Protection Agency. Correspondence. March 14, 1983.
- 14. Rivetna, R.M., National Can Corporation, to Gayle Leader, Pennsylvania Department of Environmental Resources. Correspondence. April 27, 1983.
- 15. Lunsk, Lawrence H., Pennsylvania Department of Environmental Resources, to Patrick Dettorre, National Can Corporation. Notice of Violation. November 17, 1983.
- 16. Rivetna, R.M., National Can Corporation, to Gary Bonner, Pennsylvania Department of Environmental Resources. Correspondence. April 11, 1984.
- 17. Lunsk, Lawrence H., Pennsylvania Department of Environmental Resources, to R.M. Rivetna, National Can Corporation. Correspondence. July 19, 1984.
- 18. Pennsylvania Department of Environmental Resources, Bureau of Community Environmental Control. Sanitary Survey Form for Lower Bucks County Joint Municipal Authority. August 10, 1983.
- Huxley, Robert, Supervisor, Lower Bucks County Joint Municipal Authority, with David Doran,
   NUS FIT 3. Telecon. July 20, 1987.
- 20. Cole, Henry M., Executive Director, Township of Falls Authority, to Garth Glenn, NUS FIT 3. Correspondence. June, 1987.
- 21. Pennsylvania Department of Environmental Resources, Bureau of Community Environmental Control. Sanitary Survey Form for Morrisville Borough Authority. October 29, 1986.
- 22. Wilhelm, John, Superintendent, Morrisville Borough Authority, with David Doran, NUS FIT 3. Telecon. July 20, 1987.

TDD No.: F3-8903-38

23. Chamberlain, Jeffrey, Production Superintendent, Pennsylvania - American Water Company, with David Doran, NUS FIT 3. Telecon. July 20, 1987.

- 24. Russo, Richard A., General Superintendent, Trenton Water Works, with David Doran, NUS FIT 3. Telecon. July 27, 1987.
- 25. Cawl, Betty, Bordentown (New Jersey) Water Company, with Lisa Lillis, NUS FIT 3. Telecon.
  November 24, 1987.
- 26. Olevich, Robert, Superintendent, Florence Water and Sewer Authority, with Charles Meyer, NUS FIT 3. Telecon. January 27, 1986.
- 27. United States Geological Survey. Trenton West, Pennsylvania New Jersey Quadrangle, 7.5 Minute Series. Map of Flood-Prone Areas. 1955.
- 28. Greenman, D.W., D.R. Rima, W.N. Lockwood, and H. Meisler, Pennsylvania Geological Survey. Groundwater Resources of the Coastal Plain Area of Southeastern Pennsylvania. Bulletin W13, 1961.
- 29. Wolfe, Peter E. Landscapes of the Coastal Plain. In <u>The Geology and Landscapes of New</u>
  Jersey. New York: Crane, Russak and Company. 1977.
- 30. Pennsylvania Department of Environmental Resources, Bureau of Topographic and Geologic Survey. Atlas of Preliminary Geologic Quadrangle Maps of Pennsylvania. Trenton West, Pennsylvania Quadrangle. 1981.
- 31. Pennsylvania Department of Environmental Resources, Bureau of Topographic and Geologic Survey. Engineering Characteristics of the Rocks of Pennsylvania. Environmental Geology Report 1, 1982.
- 32. Paulachok, Gary N., et al., United States Geological Survey. Hydrologic Data for Aquifers in Philadelphia, Pennsylvania. Open-File Report 83-149, 1984.
- Zapecza, Otto S., United States Geological Survey. Hydrogeologic Framework of the New Jersey Coastal Plain. Open-File Report 84-730, 1984.

TDD No.: <u>F3-8903-38</u>

34. United States Department of Agriculture, Soil Conservation Service. <u>Soil Survey of Bucks and Philadelphia Counties, Pennsylvania</u>. July, 1975.

- 35. United States Department of Commerce. <u>Climatography of the United States</u>. Local Climatological Data, Philadelphia, Pennsylvania. 1983.
- 36. Uncontrolled Hazardous Waste Site Ranking System; A User's Manual. One-Year, 24-Hour Rainfall (inches) (figure 8); Mean Annual Lake Evaporation (inches) (figure 4). August 1982.
- 37. National Can Corporation, Fairless Facility. Drum Storage Area Photographs. Photocopied November 1980.
- 38. Kulp, Charles J., United States Department of the Interior, Fish and Wildlife Service, to Garth Glenn, NUS FIT 3. Correspondence. June 7, 1989.
- 39. Drayton, Eugenie B., Nature Conservancy, to Garth Glenn, NUS FIT 3. Correspondence. June 30, 1989.